



Entergy Operations, Inc.
River Bend Station
5485 U. S. Highway 61
St. Francisville, LA 70775
Tel 225 381 4177
Fax 225 381 4139
jclark@entergy.com

Joseph A. Clark
Manager, Regulatory Assurance


June 29, 2015

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

RBG-47581
RBF1-15-0098

Subject: Submittal of Owner's Activity Report Form (OAR-1)
River Bend Station - Unit 1
Docket No. 50-458
License No. NPF-47

Pursuant to ASME Code Case N-532-4, please find enclosed the River Bend Station (RBS) Cycle 18 Owner's Activity Report Form (OAR-1). This report reflects ASME Section XI program activities occurring between March 2013, and March 2015. If you have any questions or require further information, please contact Ms. Angela Cockrum at (225) 381-4841.



Joseph A. Clark
Manager – Regulatory Assurance

TJB
JAC/tjb

A047
NRR


Submittal of OAR-1 Form
RBG-47367
Page 2 of 2

cc: U.S. Nuclear Regulatory Commission
Region IV
1600 E. Lamar Blvd.
Arlington, TX 76011-4511

NRC Resident Inspector
PO Box 1050
St. Francisville, LA 70775

Central Records Clerk
Public Utility Commission of Texas
1701 N. Congress Ave.
Austin, TX 78711-3326

Mr. Alan Wang, Project Manager
U.S. Nuclear Regulatory Commission
MS O-8B1
11555 Rockville Pike
Rockville, MD 20852-2738

Ji Young Wiley
Louisiana Department of Environmental Quality
Office of Environmental Quality
P. O. Box 4312
Baton Rouge, LA 70821-4312

FORM OAR-1 OWNERS ACTIVITY REPORT

Page 1 of 2

Report Number Cycle 18 / Refueling Outage RF-18 OAR-1

Plant River Bend Station, 5485 U.S. Highway 61, St. Francisville, Louisiana 70775

Unit No. 1 Commercial service date 06/16/1986 Refueling outage no. RF-18
(If applicable)

Current inspection interval 3rd Inspection Interval
(1st, 2nd, 3rd, 4th, other)

Current inspection period 2nd Inspection Period
(1st, 2nd, 3rd)

Edition and Addenda of Section XI applicable to the inspection plans 2001 Edition thru 2003 Addenda

Date and revision of inspection plans SEP-ISI-RBS-001 R/O - 2/14/2013

Edition and Addenda of Section XI applicable to repair/replacement activities, if different than the inspection plans N/A

Code Cases used: N-532-5
(If applicable)

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of RF-18 conform to the requirements of Section XI. (refueling outage number)

Signed

RBS ASME R/R Engineer
Owner or Owner's Designee, Title

Date

6/25/15

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Louisiana and employed by HSB Global Standards of Hartford CT have inspected the items described in this Owner's Activity Report and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in Accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or loss of any kind arising from or connected with this inspection.

Inspector's Signature

Inspector's Signature

Commissions

LA 1184 (A.N.I.)
National Board, State, Province, and Endorsements

Date

6-25-15

Page 2 of 2

Unit No. 1 Commercial service date 06/16/1986 Refueling outage no. RF-18
(If applicable)

[illegible][illegible]