

# DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242


WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

March 23, 1981

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287  
IE Bulletin 80-11




Dear Sir:

This letter supplements my letters of July 7, October 28, November 4, 1980, and February 2, 9, and February 26, 1981.

The initial site surveillance of masonry walls at Oconee Nuclear Station was conducted during June, 1980, while Unit Two was in operation. As a consequence, Unit Two's Reactor Building was not accessible for survey of masonry walls. The unit was recently taken out of service for maintenance and the Reactor Building was surveyed in accordance with established procedures. No masonry walls were found.

Very truly yours,

  
William O. Parker, Jr.

FTP:pw

cc: Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8104090038

Q