

INSERVICE INSPECTION REPORT

**UNIT 2 OCONEE 1993 REFUELING
OUTAGE 13**

Location: Hwy 130/183, Seneca, South Carolina 29679

NRC Docket No. 50-270

Commercial Service Date: September 9, 1974

**Owner: Duke Power Company
526 S. Church St.
Charlotte, N. C. 28201-1006**

Revision 1

Prepared By: R. L. Rouse **Date** 11/2/94
Reviewed By: Jim Baylman **Date** 11/2/94
Approved By: J. B. Barlowe **Date** 11/8/94

Copy No. 2 **Assigned To** NRC Document Control

Controlled X **Uncontrolled**

CONTROLLED DISTRIBUTION

Copy No.

Assigned To

Original

Duke Power Company Quality
Assurance Technical Services

1

Oconee Component Engineering

2

NRC Document Control

UNCONTROLLED DISTRIBUTION

3

Hartford Steam Boiler Inspection
and Insurance Company (AIA)
c/o C. A. Ireland

TABLE OF CONTENTS

<u>Section</u>	<u>Title</u>	<u>Revision</u>
1.	<i>General Information</i>	0
2.	<i>Summary of Inservice Inspections for Outage 13</i>	1
3.	<i>Second Ten Year Inspection Status</i>	0
4.	<i>Final Inservice Inspection Plan for Outage 13</i>	0
5.	<i>Results of Inspections Performed During Outage 13</i>	0
6.	<i>Reportable Indications</i>	0
7.	<i>Personnel, Equipment, and Material Certifications</i>	0
8.	<i>Corrective Action</i>	0
9.	<i>Reference Documents</i>	0
10.	<i>Class 1 and 2 Repairs and Replacements</i>	0

Augmented Inspections (Continued)

<i>Item Number</i>	<i>Description</i>	<i>Total Scheduled During Outage</i>	<i>Total Examined During Outage</i>
E10.001	Pressurizer Sensing/ Sampling Nozzle Safe Ends	0	0
TOTALS		19	19

A detailed description of each examination listed in Sections 2.1 through 2.3 are located in Section 3 of this report. Results of each examination are located in Section 4 of this report.