



Number: 279

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—	_____	Motor (wiring)	✓	—	—	_____
Brakes	✓	—	—	_____	Radiator	✓	—	—	_____
Horn	✓	—	—	_____	Belts	✓	—	—	_____
Lights	✓	—	—	_____	Hoses	✓	—	—	_____
Clutch	—	—	✓	_____					
Windshield Wiper	✓	—	—	_____					
Glass	✓	—	—	_____					
					Shop				
Rear View Mirror	✓	—	—	_____	Equipment				
Body	✓	—	—	_____	Lubrication Points	✓	—	—	_____
Cover	✓	—	—	_____	Loose Bearings	—	—	✓	_____
Frame	✓	—	—	_____	Guards	✓	—	—	_____
Dump Mechanism	—	—	✓	_____	Belt Tension	✓	—	—	_____
Steering	✓	—	—	_____	Loose Gears	—	—	✓	_____
Fire Extinguisher	✓	—	—	_____	Brakes	—	—	✓	_____
Signal System	✓	—	—	_____	Vibration	✓	—	—	_____
Fuel & Gas Lines	✓	—	—	_____	Pneu. Interlocks	✓	—	—	_____
Fuel Tank	✓	—	—	_____	Exhaust System	✓	—	—	_____
Exhaust System	✓	—	—	_____	Proper RPM	✓	—	—	_____
Boom	—	—	✓	_____	Overload Protect	✓	—	—	_____
Boom Hoist	—	—	✓	_____	Mech. Switch	✓	—	—	_____
					Ground				
Sheaves	—	—	✓	_____	Continuity	✓	—	—	_____
Hooks,	—	—	✓	_____	Limit Switches	✓	—	—	_____
Grab Bars, Steps	✓	—	—	_____	Cords	✓	—	—	_____
Warning Lights	✓	—	—	_____	Plugs/Receptacles	✓	—	—	_____



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/5/19

Equipment Name: MTL w brush cutter

Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
Rear View Mirror	—	✓	—	Needs to be tightened	Shop Equipment				
Body	✓	—	—		Air compressor				
Cover	✓	—	—		Lubrication Points	✓	—	—	
Frame	✓	—	—		Loose Bearings	—	—	✓	
Dump Mechanism	—	—	✓		Guards	✓	—	—	
Steering	✓	—	—		Belt Tension	✓	—	—	
Fire Extinguisher	✓	—	—		Loose Gears	—	—	✓	
Signal System	✓	—	—		Brakes	—	—	✓	
Fuel & Gas Lines	✓	—	—		Vibration	✓	—	—	
Fuel Tank	✓	—	—		Pneu. Interlocks	✓	—	—	
Exhaust System	✓	—	—		Exhaust System	✓	—	—	
Boom	—	—	✓		Proper RPM	✓	—	—	
Boom Hoist	—	—	✓		Overload Protect	✓	—	—	
					Mech. Switch	✓	—	—	
Sheaves	—	—	✓		Ground				
Hooks,	—	—	✓		Continuity	✓	—	—	
Grab Bars, Steps	✓	—	—		Limit Switches	✓	—	—	
Warning Lights	✓	—	—		Cords	✓	—	—	
					Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/6/14

Equipment Name: MTL ~ brush cutter

Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	—	✓	—	During work hydraulic lift line broke. Machine removed from site.
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				Air Compressor
Rear View Mirror	✓	—	—		Lubrication Points	✓	—	—	
Body	✓	—	—		Loose Bearings	—	—	✓	
Cover	✓	—	—		Guards	✓	—	—	
Frame	✓	—	—		Belt Tension	✓	—	—	
Dump Mechanism	—	—	✓		Loose Gears	—	—	✓	
Steering	✓	—	—		Brakes	—	—	✓	
Fire Extinguisher	✓	—	—		Vibration	✓	—	—	
Signal System	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	✓	—	—	
Fuel Tank	✓	—	—		Proper RPM	✓	—	—	
Exhaust System	✓	—	—		Overload Protect	✓	—	—	
Boom	—	—	✓		Mech. Switch	✓	—	—	
Boom Hoist	—	—	✓		Ground	✓	—	—	
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



Project Location: Great Kills NY

Date of Inspection: 1/6/14

Number: 289

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—	Tightened tracks	Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop				
Rear View Mirror	✓	—	—		Equipment				
Body	✓	—	—		Generator	✓	—	—	
Cover	✓	—	—		Lubrication Points	✓	—	—	
Frame	✓	—	—		Loose Bearings	—	—	✓	
Dump Mechanism	—	—	✓		Guards	✓	—	—	
Steering	✓	—	—		Belt Tension	✓	—	—	
Fire Extinguisher	✓	—	—		Loose Gears	—	—	✓	
Signal System	✓	—	—		Brakes	✓	—	✓	
Fuel & Gas Lines	✓	—	—		Vibration	✓	—	—	
Fuel Tank	✓	—	—		Pneu. Interlocks	✓	—	—	
Exhaust System	✓	—	—		Exhaust System	✓	—	—	
Boom	—	—	✓		Proper RPM	✓	—	—	
Boom Hoist	—	—	✓		Overload Protect	✓	—	—	
					Mech. Switch	✓	—	—	
Sheaves	—	—	✓		Ground	✓	—	—	
Hooks,	—	—	✓		Continuity	✓	—	—	
Grab Bars, Steps	✓	—	—		Limit Switches	✓	—	—	
Warning Lights	✓	—	—		Cords	✓	—	—	
					Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/6/14

Equipment Name: MTL ~ Mulcher

Number: 279 high flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		No other equipment currently used				
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	—	—	✓		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
					Ground	—	—	—	
Sheaves	—	—	✓		Continuity	—	—	—	
Hooks,	—	—	✓		Limit Switches	—	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/7/14

Equipment Name: MTL ~ Mulcher

Number: 279 High Flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	—	—	✓						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Generator				
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	—	—	✓	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground				
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/7/14
Equipment Name: MTL ~ brush cutter	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Air compressor				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration			✓	
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
					Ground	✓			
Sheaves			✓		Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/8/14

Equipment Name: MTL 289 w brush cutter

Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	✗		Greased joints / cleaned undercarriage				
Windshield Wiper	✓	—	—						
Glass	✓	—	—		Generator				
					Shop Equipment				
Rear View Mirror	✓	—	—		Lubrication Points	✓	—	—	
Body	✓	—	—		Loose Bearings	—	—	✓	
Cover	✓	—	—		Guards	✓	—	—	
Frame	✓	—	—		Belt Tension	✓	—	—	
Dump Mechanism	—	—	✓		Loose Gears	—	—	✓	
Steering	✓	—	—		Brakes	—	—	✓	
Fire Extinguisher	✓	—	—		Vibration	✓	—	—	
Signal System	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	✓	—	—	
Fuel Tank	✓	—	—		Proper RPM	✓	—	—	
Exhaust System	✓	—	—		Overload Protect	✓	—	—	
Boom	—	—	✓		Mech. Switch	✓	—	—	
Boom Hoist	—	—	✓		Ground	✓	—	—	
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/8/14

Equipment Name: MTL 279 High Flow

Number: 279 with ~~underwater~~ mulcher

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Air Compressor				
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground	✓	—	—	
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/9/14

Equipment Name: MTL w Mulcher

Number: 229

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	Tightened Fittings
Clutch	—	—	✓						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				Generator/Chain saw
Rear View Mirror	✓	—	—		Lubrication Points	✓	—	—	
Body	✓	—	—		Loose Bearings	—	—	✓	
Cover	✓	—	—		Guards	✓	—	—	
Frame	✓	—	—		Belt Tension	✓	—	—	
Dump Mechanism	—	—	✓		Loose Gears	—	—	✓	
Steering	✓	—	—		Brakes	✓	—	—	
Fire Extinguisher	✓	—	—		Vibration	✓	—	—	
Signal System	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	✓	—	—	
Fuel Tank	✓	—	—		Proper RPM	✓	—	—	
Exhaust System	✓	—	—		Overload Protect	✓	—	—	
Boom	—	—	✓		Mech. Switch	✓	—	—	
Boom Hoist	—	—	✓		Ground	✓	—	—	
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/9/14

Equipment Name: MTL 289 - brushcutter

Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	Replaced fitting on brush cutter hose
Clutch	—	—	✓						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				Air Compressor
Rear View Mirror	✓	—	—		Lubrication Points	✓	—	—	
Body	✓	—	—		Loose Bearings	—	—	✓	
Cover	✓	—	—		Guards	✓	—	—	
Frame	✓	—	—		Belt Tension	✓	—	—	
Dump Mechanism	—	—	✓		Loose Gears	—	—	✓	
Steering	✓	—	—		Brakes	✓	—	—	
Fire Extinguisher	✓	—	—		Vibration	✓	—	—	
Signal System	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	✓	—	—	
Fuel Tank	✓	—	—		Proper RPM	✓	—	—	
Exhaust System	✓	—	—		Overload Protect	✓	—	—	
Boom	—	—	✓		Mech. Switch	✓	—	—	
Boom Hoist	—	—	✓		Ground	✓	—	—	
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/10/14

Equipment Name: KTL ✓ Mulcher

Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	—	—	✓						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop				
Rear View Mirror	✓	—	—		Equipment				
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground				
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	

Generator



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/10/14
Equipment Name: MTL 289 ✓ brush cutter	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	—	—	✓						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Air compressor				
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	✓	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground				
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/13/14

Equipment Name: MTL w brush cutter

Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	✓						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Chain Saw				
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground				
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	✓	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	✓	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/13/14
Equipment Name: MTL ✓ mulcher	Number: 279 High Flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	✓						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—						No other equipment used
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	—	—	✓		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
Sheaves	—	—	✓		Ground	—	—	—	
Hooks,	—	—	✓		Continuity	—	—	—	
Grab Bars, Steps	✓	—	—		Limit Switches	—	—	—	
Warning Lights	✓	—	—		Cords	—	—	—	
					Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/14/14

Equipment Name: MTL ~ Brush cutter

Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	✓		Brush cutter damaged being replaced				
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				Chainsaw
Rear View Mirror	✓	—	—		Lubrication Points	✓	—	—	
Body	✓	—	—		Loose Bearings	—	—	✓	
Cover	✓	—	—		Guards	✓	—	—	
Frame	✓	—	—		Belt Tension	✓	—	—	
Dump Mechanism	—	—	✓		Loose Gears	—	—	✓	
Steering	✓	—	—		Brakes	✓	—	—	
Fire Extinguisher	✓	—	—		Vibration	✓	—	—	
Signal System	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	✓	—	—	
Fuel Tank	✓	—	—		Proper RPM	✓	—	—	
Exhaust System	✓	—	—		Overload Protect	✓	—	—	
Boom	—	—	✓		Mech. Switch	✓	—	—	
Boom Hoist	—	—	✓		Ground	—	—	✓	
Sheaves	—	—	✓		Continuity	—	—	✓	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	✓	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	✓	



	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Track cat broken	Motor (wiring)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Radiator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Hoses	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Clutch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Still operable but damaged track machine will need to be replaced.				
Windshield Wiper	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>						
Glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>						
Shop Equipment						Compressor/generator			
Rear View Mirror	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Lubrication Points	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Body	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Loose Bearings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Cover	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Guards	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Frame	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Belt Tension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Dump Mechanism	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		Loose Gears	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Brakes	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Fire Extinguisher	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Vibration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Signal System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Pneu. Interlocks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Fuel & Gas Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Exhaust System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Fuel Tank	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Proper RPM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Exhaust System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Overload Protect	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Boom	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		Mech. Switch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Boom Hoist	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		Ground	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Sheaves	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		Continuity	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Hooks,	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>		Limit Switches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Grab Bars, Steps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Cords	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Warning Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Plugs/Receptacles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/15/14

Equipment Name: 1TL ~ Brush cutter

Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—						<i>No other equipment used</i>
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	—	—	✓		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
			✓		Ground	—	—	—	
Sheaves	—	—	✓		Continuity	—	—	—	
Hooks,	—	—	✓		Limit Switches	—	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/15/14
Equipment Name: MTL ✓ Brush cutter	Number: 259

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Chain Saw	✓	—	—	
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground	✓	—	—	
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52

Project Location: Great Kills NY

Inspected by: DJH/JWV

Date of Inspection: 1/15/14

Equipment Name: 172 w mulcher

Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	—	✓	—	Broken right track unusable getting replaced	Motor (wiring)	✓	—	—	—
Brakes	✓	—	—	—	Radiator	✓	—	—	—
Horn	✓	—	—	—	Belts	✓	—	—	—
Lights	✓	—	—	—	Hoses	—	—	—	—
Clutch	✓	—	—	—					
Windshield Wiper	✓	—	—	—					
Glass	✓	—	—	—					
					Shop Equipment				No other equipment used
Rear View Mirror	✓	—	—	—	Lubrication Points	—	—	—	—
Body	✓	—	—	—	Loose Bearings	—	—	—	—
Cover	✓	—	—	—	Guards	—	—	—	—
Frame	✓	—	—	—	Belt Tension	—	—	—	—
Dump Mechanism	—	—	✓	—	Loose Gears	—	—	—	—
Steering	✓	—	—	—	Brakes	—	—	—	—
Fire Extinguisher	✓	—	—	—	Vibration	—	—	—	—
Signal System	✓	—	—	—	Pneu. Interlocks	—	—	—	—
Fuel & Gas Lines	✓	—	—	—	Exhaust System	—	—	—	—
Fuel Tank	✓	—	—	—	Proper RPM	—	—	—	—
Exhaust System	✓	—	—	—	Overload Protect	—	—	—	—
Boom	—	—	✓	—	Mech. Switch	—	—	—	—
Boom Hoist	—	—	✓	—	Ground	—	—	—	—
Sheaves	—	—	✓	—	Continuity	—	—	—	—
Hooks,	—	—	✓	—	Limit Switches	—	—	—	—
Grab Bars, Steps	✓	—	—	—	Cords	—	—	—	—
Warning Lights	✓	—	—	—	Plugs/Receptacles	—	—	—	—



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/16/14
Equipment Name: MTL w brush cutter	Number: 259

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Chain saw				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
					Ground				
Sheaves			✓		Continuity			✓	
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords			✓	
Warning Lights	✓				Plugs/Receptacles			✓	



BrightFields, Inc.

Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/16/14
Equipment Name: MTL 274 High Flow	Number: 279

Switched for MTL 274 High Flow w/ trailer

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
Rear View Mirror	—	—	✓	No mirror	Shop Equipment				Air Compressor
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
Sheaves	—	—	✓		Ground	✓	—	—	
Hooks,	—	—	✓		Continuity	✓	—	—	
Grab Bars, Steps	✓	—	—		Limit Switches	✓	—	—	
Warning Lights	✓	—	—		Cords	✓	—	—	
					Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/16/14
Equipment Name: MTL w brush cutter	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—	Getting worn	Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Generator				
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground	✓	—	—	
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/17/14
Equipment Name: MTW w brush cutter	Number: 288 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—	Gettag van	Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Air Compressor				
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground	✓	—	—	
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/17/14
Equipment Name: MTH v brush cutter	Number: 259

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Generator				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓		✓		Proper RPM	✓			
Boom	✓		✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
					Ground	✓			
Sheaves			✓		Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/17/14
Equipment Name: 172 - mulcher	Number: 279 High Flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	—	✓	—	Broken by branch					
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—						No other equipment
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	—	—	✓		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
					Ground	—	—	—	
Sheaves	—	—	✓		Continuity	—	—	—	
Hooks,	—	—	✓		Limit Switches	—	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/31/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop	N/A			
Rear View Mirror	✓	—	—		Equipment				
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	✓	—	—		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	✓	—	—		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
					Ground	—	—	—	
Sheaves	—	—	✓		Continuity	—	—	—	
Hooks,	—	—	✓		Limit Switches	—	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/31/14
Equipment Name: MTL ~ mulcher	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓							
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓		✓		Chainsaw				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings	✓		✓	
Frame	✓				Guards	✓			
Dump Mechanism	✓		✓		Belt Tension	✓			
Steering	✓				Loose Gears	✓		✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground	✓			
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/31/14
Equipment Name: MTZ ✓ grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	—	✓	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—			N/A			
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	—	—	✓		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
Sheaves	—	—	✓		Ground Continuity	—	—	—	
Hooks,	—	—	✓		Limit Switches	—	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/30/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Chain saw				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom	✓		✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
					Ground	✓			
Sheaves			✓		Continuity	✓			
Hooks,	✓		✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/30/14
Equipment Name: MTL w grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	✓	—						
Glass	✓	—	—						
					Shop Equipment	N/A			
Rear View Mirror	✓	—	—		Lubrication Points	—	—	—	
Body	✓	—	—		Loose Bearings	—	—	—	
Cover	✓	—	—		Guards	—	—	—	
Frame	✓	—	—		Belt Tension	—	—	—	
Dump Mechanism	✓	—	✓		Loose Gears	—	—	—	
Steering	✓	—	—		Brakes	—	—	—	
Fire Extinguisher	✓	—	—		Vibration	—	—	—	
Signal System	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	—	—	—	
Fuel Tank	✓	—	—		Proper RPM	—	—	—	
Exhaust System	✓	—	—		Overload Protect	—	—	—	
Boom	—	—	✓		Mech. Switch	—	—	—	
Boom Hoist	—	—	✓		Ground	—	—	—	
					Continuity	—	—	—	
Sheaves	—	—	✓		Limit Switches	—	—	—	
Hooks,	—	—	✓		Cords	—	—	—	
Grab Bars, Steps	✓	—	—		Plugs/Receptacles	—	—	—	
Warning Lights	✓	—	—						



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/30/14
Equipment Name: MTL w mulcher	Number: 279

Not used
today

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	—	—	—		Motor (wiring)	—	—	—	
Brakes	—	—	—		Radiator	—	—	—	
Horn	—	—	—		Belts	—	—	—	
Lights	—	—	—		Hoses	—	—	—	
Clutch	—	—	—						
Windshield Wiper	—	—	—						
Glass	—	—	—						
					Shop Equipment				
Rear View Mirror	—	—	—		Lubrication Points	—	—	—	
Body	—	—	—		Loose Bearings	—	—	—	
Cover	—	—	—		Guards	—	—	—	
Frame	—	—	—		Belt Tension	—	—	—	
Dump Mechanism	—	—	—		Loose Gears	—	—	—	
Steering	—	—	—		Brakes	—	—	—	
Fire Extinguisher	—	—	—		Vibration	—	—	—	
Signal System	—	—	—		Pneu. Interlocks	—	—	—	
Fuel & Gas Lines	—	—	—		Exhaust System	—	—	—	
Fuel Tank	—	—	—		Proper RPM	—	—	—	
Exhaust System	—	—	—		Overload Protect	—	—	—	
Boom	—	—	—		Mech. Switch	—	—	—	
Boom Hoist	—	—	—		Ground	—	—	—	
Sheaves	—	—	—		Continuity	—	—	—	
Hooks,	—	—	—		Limit Switches	—	—	—	
Grab Bars, Steps	—	—	—		Cords	—	—	—	
Warning Lights	—	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/29/14
Equipment Name: MTL w mulder	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights		✓			Hoses	✓			
Clutch	✓								
Windshield Wiper		✓							
Glass	✓								
Rear View Mirror			✓		Shop Equipment				chainsaw
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground				
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/29/14
Equipment Name: MTL w grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓							
Glass	✓								
					Shop Equipment				None
Rear View Mirror	✓				Lubrication Points				
Body	✓				Loose Bearings				
Cover	✓				Guards				
Frame	✓				Belt Tension				
Dump Mechanism			✓		Loose Gears				
Steering	✓				Brakes				
Fire Extinguisher	✓				Vibration				
Signal System	✓				Pneu. Interlocks				
Fuel & Gas Lines	✓				Exhaust System				
Fuel Tank	✓				Proper RPM				
Exhaust System	✓				Overload Protect				
Boom			✓		Mech. Switch				
Boom Hoist			✓		Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/29/14
Equipment Name: Excavator	Number: Excavator 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓					N/A			
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism	✓				Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom	✓				Overload Protect				
Boom Hoist			✓		Mech. Switch				
					Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				

7803



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/28/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				N/A
Rear View Mirror	✓				Lubrication Points				
Body	✓				Loose Bearings				
Cover	✓				Guards				
Frame	✓				Belt Tension				
Dump Mechanism			✓		Loose Gears				
Steering	✓				Brakes				
Fire Extinguisher	✓				Vibration				
Signal System	✓				Pneu. Interlocks				
Fuel & Gas Lines	✓				Exhaust System				
Fuel Tank	✓				Proper RPM				
Exhaust System	✓				Overload Protect				
Boom	✓				Mech. Switch				
Boom Hoist			✓		Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/28/14
Equipment Name: MTL w Mulder	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			Fixed
Clutch	✓								
Windshield Wiper	✓	✓	✓						
Glass	✓								
					Shop Equipment				Chainsaws
Rear View Mirror			✓		Lubrication Points	✓			
Body	✓				Loose Bearings	✓		✓	
Cover	✓				Guards	✓			
Frame	✓				Belt Tension	✓			
Dump Mechanism			✓		Loose Gears			✓	
Steering	✓				Brakes	✓			
Fire Extinguisher	✓				Vibration	✓			
Signal System	✓				Pneu. Interlocks	✓			
Fuel & Gas Lines	✓				Exhaust System	✓			
Fuel Tank	✓				Proper RPM	✓			
Exhaust System	✓				Overload Protect	✓			
Boom			✓		Mech. Switch	✓			
Boom Hoist			✓		Ground	✓			
Sheaves			✓		Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/28/14
Equipment Name: MTL ~ grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓			Worn	Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper		✓		Broken					
Glass	✓								
Rear View Mirror	✓				Shop Equipment			N/A	
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom			✓		Overload Protect				
Boom Hoist			✓		Mech. Switch				
Sheaves			✓		Ground				
Hooks,			✓		Continuity				
Grab Bars, Steps	✓				Limit Switches				
Warning Lights	✓				Cords				
					Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/27/14
Equipment Name: MTL w grapple bucket	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper		✓							
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Chainsaw				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground	✓			
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/27/14
Equipment Name: Mth w grapple/mulcher	Number: 279 high flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights		✓		Two broken lights rear	Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓							
Glass	✓								
Rear View Mirror	✓	✓	✓		Shop Equipment				
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom			✓		Overload Protect				
Boom Hoist			✓		Mech. Switch				
Sheaves			✓		Ground				
Hooks,			✓		Continuity				
Grab Bars, Steps	✓				Limit Switches				
Warning Lights	✓				Cords				
					Plugs/Receptacles				

Delivered on site



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/27/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop				
Rear View Mirror	✓				Equipment				
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom	✓				Overload Protect				
Boom Hoist	✓				Mech. Switch				
					Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/24/14
Equipment Name: MTL w Mulcher	Number: 279 High Flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
Rear View Mirror			✓		Shop Equipment				No other used
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom			✓		Overload Protect				
Boom Hoist			✓		Mech. Switch				
Sheaves			✓		Ground				
Hooks,			✓		Continuity				
Grab Bars, Steps	✓				Limit Switches				
Warning Lights	✓				Cords				
					Plugs/Receptacles				



BrightFields, Inc.

Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/24/14
Equipment Name: MTL w grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓			Getting worn	Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓							
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Chainsaw	✓			
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/23/14
Equipment Name: <i>MTL w grapple</i>	Number: <i>289</i>

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓		<i>Broken</i>					
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				<i>chainsaw</i>				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓		✓	
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground	✓			
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/23/14
Equipment Name: MTL w mulcher	Number: 279 High Flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper		✓		Brake from branch					
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓		✓		Lubrication Points				
Body	✓				Loose Bearings				
Cover	✓				Guards				
Frame	✓				Belt Tension				
Dump Mechanism			✓		Loose Gears				
Steering	✓				Brakes				
Fire Extinguisher	✓				Vibration				
Signal System	✓				Pneu. Interlocks				
Fuel & Gas Lines	✓				Exhaust System				
Fuel Tank	✓				Proper RPM				
Exhaust System	✓				Overload Protect				
Boom			✓		Mech. Switch				
Boom Hoist			✓		Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/22/14
Equipment Name: <i>MTL v mulcher</i>	Number: <i>279 High Flow</i>

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Lubrication Points	✓	—	—	<i>Chain Saw - New chainsaw purchased</i>
Body	✓	—	—		Loose Bearings	✓	—	✓	
Cover	✓	—	—		Guards	✓	—	—	
Frame	✓	—	—		Belt Tension	✓	—	—	
Dump Mechanism	✓	—	✓		Loose Gears	—	—	✓	
Steering	✓	—	—		Brakes	✓	—	—	
Fire Extinguisher	✓	—	—		Vibration	✓	—	—	
Signal System	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	✓	—	—	
Fuel Tank	✓	—	—		Proper RPM	✓	—	—	
Exhaust System	✓	—	—		Overload Protect	✓	—	—	
Boom	—	—	✓		Mech. Switch	✓	—	—	
Boom Hoist	—	—	✓		Ground Continuity	✓	—	—	
Sheaves	—	—	✓		Limit Switches	✓	—	—	
Hooks,	—	—	✓		Cords	✓	—	—	
Grab Bars, Steps	✓	—	—		Plugs/Receptacles	✓	—	—	
Warning Lights	✓	—	—						



BrightFields, Inc.

Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/22/14
Equipment Name: MTL ✓ grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper		✓		Branch/broke					
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Generator				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground	✓			
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/22/14
Equipment Name: <i>MTL v brush cutter</i>	Number: <i>259</i>

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				<i>Air Compressor</i>				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓		✓	
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground	✓			
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.

Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/21/14
Equipment Name: MTL ~ brush cutter	Number: 259

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—		Chain saw	—	—	—	Damaged chain
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	✓	—	—	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	✓	—	
Steering	✓	—	—		Loose Gears	—	✓	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	✓	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
Sheaves	—	—	✓		Ground	✓	—	—	
Hooks,	—	—	✓		Continuity	✓	—	—	
Grab Bars, Steps	✓	—	—		Limit Switches	✓	—	—	
Warning Lights	✓	—	—		Cords	✓	—	—	
					Plugs/Receptacles	✓	—	—	



BrightFields, Inc.

Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/21/14
Equipment Name: MTL - grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				Compressor
Rear View Mirror	✓				Lubrication Points	✓			
Body	✓				Loose Bearings	✓		✓	
Cover	✓				Guards	✓			
Frame	✓				Belt Tension	✓			
Dump Mechanism			✓		Loose Gears			✓	
Steering	✓				Brakes	✓			
Fire Extinguisher	✓				Vibration	✓			
Signal System	✓				Pneu. Interlocks	✓			
Fuel & Gas Lines	✓				Exhaust System	✓			
Fuel Tank	✓				Proper RPM	✓			
Exhaust System	✓				Overload Protect	✓			
Boom			✓		Mech. Switch	✓			
Boom Hoist			✓		Ground				
Sheaves			✓		Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/28/14
Equipment Name: MTL w mulcher	Number: 279 high flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper		✓		Damaged					
Glass	✓								
Rear View Mirror	✓		✓	None	Shop Equipment				Generator
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground				
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.

Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/20/14
Equipment Name: MTL 204 w brush cutter	Number: 259

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				Generator
Rear View Mirror	✓				Lubrication Points	✓			
Body	✓				Loose Bearings			✓	
Cover	✓				Guards	✓			
Frame	✓				Belt Tension	✓		✓	
Dump Mechanism			✓		Loose Gears			✓	
Steering	✓				Brakes	✓			
Fire Extinguisher	✓				Vibration	✓			
Signal System	✓				Pneu. Interlocks	✓			
Fuel & Gas Lines	✓				Exhaust System	✓			
Fuel Tank	✓				Proper RPM	✓			
Exhaust System	✓				Overload Protect	✓			
Boom			✓		Mech. Switch	✓			
Boom Hoist			✓		Ground	✓			
Sheaves			✓		Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/20/14
Equipment Name: MTL w grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			Broken hose on grapple bucket
Clutch	✓								Pintek make repair
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Chain saw				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
					Ground				
Sheaves			✓		Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 1/20/14
Equipment Name: 279 MTL - mulch	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓		Broken					
Glass	✓								
Rear View Mirror			✓	No mirror	Shop Equipment				Air Compressor
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓		✓	
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground	✓			
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/24/14
Equipment Name: HTZ w Mulcher	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop Equipment	N/A			
Rear View Mirror	/				Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism	/				Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom	/				Mech. Switch				
Boom Hoist	/				Ground				
Sheaves	/				Continuity				
Hooks,	/				Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/	—	—	Motor (wiring)	/	—	—		
Brakes	/	—	—	Radiator	/	—	—		
Horn	/	—	—	Belts	/	—	—		
Lights	—	/	—	Hoses	/	—	—		
Clutch	/	—	—						
Windshield Wiper	—	/	—						
Glass	/	—	—						
				Shop Equipment					
Rear View Mirror	/	—	—		Chainsaw				
Body	/	—	—	Lubrication Points	/	—	—		
Cover	/	—	—	Loose Bearings	—	—	/		
Frame	/	—	—	Guards	/	—	—		
Dump Mechanism	—	—	/	Belt Tension	/	—	—		
Steering	/	—	—	Loose Gears	—	—	/		
Fire Extinguisher	/	—	—	Brakes	/	—	—		
Signal System	/	—	—	Vibration	/	—	—		
Fuel & Gas Lines	/	—	—	Pneu. Interlocks	/	—	—		
Fuel Tank	/	—	—	Exhaust System	/	—	—		
Exhaust System	/	—	—	Proper RPM	/	—	—		
Boom	—	—	/	Overload Protect	/	—	—		
Boom Hoist	—	—	/	Mech. Switch	/	—	—		
				Ground					
Sheaves	—	—	/	Continuity	/	—	—		
Hooks,	—	—	/	Limit Switches	/	—	—		
Grab Bars, Steps	/	—	—	Cords	/	—	—		
Warning Lights	/	—	—	Plugs/Receptacles	/	—	—		



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/24/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/	/		Cracked					
Glass		/		Cracked					
					Shop Equipment	N/A			
Rear View Mirror	/				Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism			/		Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom			/		Mech. Switch				
Boom Hoist			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/25/14
Equipment Name: MTL w Grapple	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop				
Rear View Mirror			/		Equipment				Chainsaw
Body	/				Lubrication Points	/			
Cover	/				Loose Bearings			/	
Frame	/				Guards	/			
Dump Mechanism			/		Belt Tension	/			
Steering	/				Loose Gears			/	
Fire Extinguisher	/				Brakes	/			
Signal System	/				Vibration	/			
Fuel & Gas Lines	/				Pneu. Interlocks	/			
Fuel Tank	/				Exhaust System	/			
Exhaust System	/				Proper RPM	/			
Boom			/		Overload Protect	/			
Boom Hoist			/		Mech. Switch	/			
					Ground				
Sheaves			/		Continuity	/			
Hooks,			/		Limit Switches	/			
Grab Bars, Steps	/				Cords	/			
Warning Lights	/				Plugs/Receptacles	/			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/25/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/			Cracked					
					Shop Equipment	N/A			
Rear View Mirror	/				Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism			/		Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom	/				Mech. Switch				
Boom Hoist			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/27/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop				
Rear View Mirror	/				Equipment	N/A			
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism	/				Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom	/		/		Overload Protect				
Boom Hoist			/		Mech. Switch				
			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/27/14
Equipment Name: MTL v Gapple	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop				
Rear View Mirror			/		Equipment				
Body	/				Lubrication Points	/			
Cover	/				Loose Bearings			/	
Frame	/				Guards	/			
Dump Mechanism			/		Belt Tension	/			
Steering	/				Loose Gears			/	
Fire Extinguisher	/				Brakes	/			
Signal System	/				Vibration	/			
Fuel & Gas Lines	/				Pneu. Interlocks	/			
Fuel Tank	/				Exhaust System	/			
Exhaust System	/				Proper RPM	/			
Boom			/		Overload Protect	/			
Boom Hoist			/		Mech. Switch	/			
Sheaves			/		Ground	/			
Hooks,			/		Continuity	/			
Grab Bars, Steps	/				Limit Switches	/			
Warning Lights	/				Cords	/			
					Plugs/Receptacles	/			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/28/14
Equipment Name: MTZ w mulcher	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights		/		still works	Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop				N/A
Rear View Mirror			/		Equipment				
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism	/				Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom			/		Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/21/14
Equipment Name: Excavator	Number: 326

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass		/		Cracked					
					Shop				
Rear View Mirror	/				Equipment	N/A			
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism			/		Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom			/		Overload Protect				
Boom Hoist			/		Mech. Switch				
Sheaves			/		Ground				
Hooks,			/		Continuity				
Grab Bars, Steps	/				Limit Switches				
Warning Lights	/				Cords				
					Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/21/14
Equipment Name: MTL - Grapple	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights		/		working	Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop				
Rear View Mirror			/		Equipment				Chainsaw
Body	/				Lubrication Points	/			
Cover	/				Loose Bearings			/	
Frame	/				Guards	/			
Dump Mechanism			/		Belt Tension	/			
Steering	/				Loose Gears			/	
Fire Extinguisher	/				Brakes	/			
Signal System	/				Vibration	/			
Fuel & Gas Lines	/				Pneu. Interlocks	/			
Fuel Tank	/				Exhaust System	/			
Exhaust System	/				Proper RPM	/			
Boom			/		Overload Protect	/			
Boom Hoist			/		Mech. Switch	/			
Sheaves			/		Ground	/			
Hooks,			/		Continuity	/			
Grab Bars, Steps	/				Limit Switches	/			
Warning Lights	/				Cords	/			
					Plugs/Receptacles	/			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/20/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/			Cracked					
					Shop Equipment	N/A			
Rear View Mirror	/				Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism					Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom	/				Mech. Switch				
Boom Hoist			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/20/19
Equipment Name: ATT & Grapple	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights		/		Still working	Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop Equipment				
Rear View Mirror	/		/		Chainsaw				
Body	/				Lubrication Points	/			
Cover	/				Loose Bearings			/	
Frame	/				Guards	/			
Dump Mechanism			/		Belt Tension	/			
Steering	/				Loose Gears			/	
Fire Extinguisher	/				Brakes	/			
Signal System	/				Vibration	/			
Fuel & Gas Lines	/				Pneu. Interlocks	/			
Fuel Tank	/				Exhaust System	/			
Exhaust System	/				Proper RPM	/			
Boom			/		Overload Protect	/			
Boom Hoist			/		Mech. Switch	/			
					Ground				
Sheaves			/		Continuity	/			
Hooks,			/		Limit Switches	/			
Grab Bars, Steps	/				Cords	/			
Warning Lights	/				Plugs/Receptacles	/			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/19/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass		/		Cracked					
					Shop				N/A
Rear View Mirror	/				Equipment				
Body	/			Small dent	Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism			/		Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom	/				Overload Protect				
Boom Hoist			/		Mech. Switch				
Sheaves			/		Ground				
Hooks,			/		Continuity				
Grab Bars, Steps	/				Limit Switches				
Warning Lights	/				Cords				
					Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/19/14
Equipment Name: MTL w Grapple	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights		/		still working	Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop Equipment				
Rear View Mirror			/		Chain saw				
Body	/				Lubrication Points	/			
Cover	/				Loose Bearings			/	
Frame	/				Guards	/			
Dump Mechanism			/		Belt Tension	/			
Steering	/				Loose Gears			/	
Fire Extinguisher	/				Brakes	/			
Signal System	/				Vibration	/			
Fuel & Gas Lines	/				Pneu. Interlocks	/			
Fuel Tank	/				Exhaust System	/			
Exhaust System	/				Proper RPM	/			
Boom			/		Overload Protect	/			
Boom Hoist			/		Mech. Switch	/			
					Ground	/			
Sheaves			/		Continuity				
Hooks,			/		Limit Switches	/			
Grab Bars, Steps	/				Cords	/			
Warning Lights	/				Plugs/Receptacles	/			



	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop	N/A			
Rear View Mirror	/				Equipment				
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism			/		Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom					Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/18/14
Equipment Name: MTL ~ Grapple	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights		✓		still working	Hoses	✓			
Clutch	✓								
Windshield Wiper		✓							
Glass	✓								
					Shop Equipment				
Rear View Mirror			✓		Chainsaw				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings		✓		
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
					Ground				
Sheaves			✓		Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/12/14
Equipment Name: Excavator	Number: A 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop				
Rear View Mirror	✓				Equipment	N/A			
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System			✓		Proper RPM				
Boom					Overload Protect				
Boom Hoist			✓		Mech. Switch				
					Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—	<i>varn</i>	Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	—	—	✓						
Glass	✓	—	—						
					Shop				
Rear View Mirror	✓	—	—		Equipment	<i>chain saw</i>			
Body	✓	—	—		Lubrication Points	✓	—	—	
Cover	✓	—	—		Loose Bearings	—	—	✓	
Frame	✓	—	—		Guards	✓	—	—	
Dump Mechanism	—	—	✓		Belt Tension	✓	—	—	
Steering	✓	—	—		Loose Gears	—	—	✓	
Fire Extinguisher	✓	—	—		Brakes	✓	—	—	
Signal System	✓	—	—		Vibration	✓	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	✓	—	—	
Fuel Tank	✓	—	—		Exhaust System	✓	—	—	
Exhaust System	✓	—	—		Proper RPM	✓	—	—	
Boom	—	—	✓		Overload Protect	✓	—	—	
Boom Hoist	—	—	✓		Mech. Switch	✓	—	—	
					Ground				
Sheaves	—	—	✓		Continuity	✓	—	—	
Hooks,	—	—	✓		Limit Switches	✓	—	—	
Grab Bars, Steps	✓	—	—		Cords	✓	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	✓	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/11/14
Equipment Name: MTL w brush cutter	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop				
Rear View Mirror	/				Equipment				
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism			/		Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom			/		Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/11/14
Equipment Name: <i>MTL - Mulder</i>	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	—	✓	—	<i>Rear broken button</i>	Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	—	✓	—						
Glass	✓	—	—						
Rear View Mirror	—	—	✓		Shop Equipment	N/A			
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	—	—	✓		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
Sheaves	—	—	✓		Ground	—	—	—	
Hooks,	—	—	✓		Continuity	—	—	—	
Grab Bars, Steps	✓	—	—		Limit Switches	—	—	—	
Warning Lights	✓	—	—		Cords	—	—	—	
					Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/10/14
Equipment Name: 15L - Mulcher	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights		/			Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop				
Rear View Mirror			/		Equipment				
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism	/				Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom			/		Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/10/14
Equipment Name: MTZ w brushcutter	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop				
Rear View Mirror	/				Equipment	N/A			
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism			/		Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom			/		Overload Protect				
Boom Hoist			/		Mech. Switch				
			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/10/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment				
Rear View Mirror	✓				Chainsaw				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings	✓		✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom	✓				Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
					Ground	✓			
Sheaves			✓		Continuity	✓			
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/	—	—	_____	Motor (wiring)	/	—	—	_____
Brakes	/	—	—	_____	Radiator	/	—	—	_____
Horn	/	—	—	_____	Belts	/	—	—	_____
Lights	/	—	—	_____	Hoses	/	—	—	_____
Clutch	/	—	—	_____					
Windshield Wiper	/	—	—	_____					
Glass	/	—	—	_____					
					Shop				
Rear View Mirror	/	—	—	_____	Equipment				
Body	/	—	—	_____	Lubrication Points	—	—	—	_____
Cover	/	—	—	_____	Loose Bearings	—	—	—	_____
Frame	/	—	—	_____	Guards	—	—	—	_____
Dump Mechanism	—	—	/	_____	Belt Tension	—	—	—	_____
Steering	/	—	—	_____	Loose Gears	—	—	—	_____
Fire Extinguisher	/	—	—	_____	Brakes	—	—	—	_____
Signal System	/	—	—	_____	Vibration	—	—	—	_____
Fuel & Gas Lines	/	—	—	_____	Pneu. Interlocks	—	—	—	_____
Fuel Tank	/	—	—	_____	Exhaust System	—	—	—	_____
Exhaust System	/	—	—	_____	Proper RPM	—	—	—	_____
Boom	/	—	—	_____	Overload Protect	—	—	—	_____
Boom Hoist	—	—	/	_____	Mech. Switch	—	—	—	_____
					Ground	—	—	—	_____
Sheaves	—	—	/	_____	Continuity	—	—	—	_____
Hooks,	—	—	/	_____	Limit Switches	—	—	—	_____
Grab Bars, Steps	/	—	—	_____	Cords	—	—	—	_____
Warning Lights	/	—	—	_____	Plugs/Receptacles	—	—	—	_____



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/7/2014
Equipment Name: MTZ w Mulcher	Number: 279 HighFlow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓			Broken but working	Hoses		✓		O-ring on hose fitting broken
Clutch	✓								unusable will repair Monday
Windshield Wiper		✓							
Glass	✓								
					Shop Equipment				
Rear View Mirror			✓		chainsaw				
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist					Mech. Switch	✓			
					Ground	✓			
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches	✓			
Grab Bars, Steps	✓				Cords	✓			
Warning Lights	✓				Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/7/14
Equipment Name: MTL ✓ brush cutter	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper		✓							
Glass	✓								
					Shop Equipment	N/A			
Rear View Mirror	✓				Lubrication Points				
Body	✓				Loose Bearings				
Cover	✓				Guards				
Frame	✓				Belt Tension				
Dump Mechanism			✓		Loose Gears				
Steering	✓				Brakes				
Fire Extinguisher	✓				Vibration				
Signal System	✓				Pneu. Interlocks				
Fuel & Gas Lines	✓				Exhaust System				
Fuel Tank	✓				Proper RPM				
Exhaust System	✓				Overload Protect				
Boom			✓		Mech. Switch				
Boom Hoist			✓		Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/6/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment	N/A			
Rear View Mirror	✓	—	—		Lubrication Points	—	—	—	
Body	✓	—	—		Loose Bearings	—	—	—	
Cover	✓	—	—		Guards	—	—	—	
Frame	✓	—	—		Belt Tension	—	—	—	
Dump Mechanism	✓	—	—		Loose Gears	—	—	—	
Steering	✓	—	—		Brakes	—	—	—	
Fire Extinguisher	✓	—	—		Vibration	—	—	—	
Signal System	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	—	—	—	
Fuel Tank	✓	—	—		Proper RPM	—	—	—	
Exhaust System	✓	—	—		Overload Protect	—	—	—	
Boom	✓	—	—		Mech. Switch	—	—	—	
Boom Hoist	—	—	✓		Ground	—	—	—	
Sheaves	—	—	✓		Continuity	—	—	—	
Hooks,	—	—	✓		Limit Switches	—	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/6/14
Equipment Name: MTL w Mulcher	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights		✓		still working	Hoses	✓			
Clutch	✓								
Windshield Wiper		✓							
Glass	✓								
Rear View Mirror			✓		Shop Equipment				Chain saw
Body	✓				Lubrication Points	✓			
Cover	✓				Loose Bearings			✓	
Frame	✓				Guards	✓			
Dump Mechanism			✓		Belt Tension	✓			
Steering	✓				Loose Gears			✓	
Fire Extinguisher	✓				Brakes	✓			
Signal System	✓				Vibration	✓			
Fuel & Gas Lines	✓				Pneu. Interlocks	✓			
Fuel Tank	✓				Exhaust System	✓			
Exhaust System	✓				Proper RPM	✓			
Boom			✓		Overload Protect	✓			
Boom Hoist			✓		Mech. Switch	✓			
Sheaves			✓		Ground	✓			
Hooks,			✓		Continuity	✓			
Grab Bars, Steps	✓				Limit Switches	✓			
Warning Lights	✓				Cords	✓			
					Plugs/Receptacles	✓			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/6/14
Equipment Name: MTL ✓ Grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	✓	—						
Glass	✓	—	—						
					Shop Equipment	N/A			
Rear View Mirror	✓	—	—		Lubrication Points	—	—	—	
Body	✓	—	—		Loose Bearings	—	—	—	
Cover	✓	—	—		Guards	—	—	—	
Frame	✓	—	—		Belt Tension	—	—	—	
Dump Mechanism	—	—	✓		Loose Gears	—	—	—	
Steering	✓	—	—		Brakes	—	—	—	
Fire Extinguisher	✓	—	—		Vibration	—	—	—	
Signal System	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	—	—	—	
Fuel Tank	✓	—	—		Proper RPM	—	—	—	
Exhaust System	✓	—	—		Overload Protect	—	—	—	
Boom	—	—	✓		Mech. Switch	—	—	—	
Boom Hoist	—	—	✓		Ground	—	—	—	
					Continuity	—	—	—	
Sheaves	—	—	✓		Limit Switches	—	—	—	
Hooks,	—	—	✓		Cords	—	—	—	
Grab Bars, Steps	✓	—	—		Plugs/Receptacles	—	—	—	
Warning Lights	✓	—	—						



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/5/14
Equipment Name: MTL ✓ Crapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	—	✓	—						
Glass	✓	—	—						
					Shop Equipment				
Rear View Mirror	✓	—	—			N/A			
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	—	—	✓		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
					Ground	—	—	—	
Sheaves	—	—	✓		Continuity	—	—	—	
Hooks,	—	—	✓		Limit Switches	—	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/5/14
Equipment Name: MTL w Mulcher	Number: 279 HighFlow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓	✓			Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓							
Glass	✓								
Rear View Mirror			✓		Shop Equipment	N/A			
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom			✓		Overload Protect				
Boom Hoist			✓		Mech. Switch				
Sheaves			✓		Ground				
Hooks,			✓		Continuity				
Grab Bars, Steps	✓				Limit Switches				
Warning Lights	✓				Cords				
					Plugs/Receptacles				



	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—	_____	Motor (wiring)	✓	—	—	_____
Brakes	✓	—	—	_____	Radiator	✓	—	—	_____
Horn	✓	—	—	_____	Belts	✓	—	—	_____
Lights	✓	—	—	_____	Hoses	✓	—	—	_____
Clutch	✓	—	—	_____					
Windshield Wiper	✓	—	—	_____					
Glass	✓	—	—	_____					
					Shop				
					Equipment				
Rear View Mirror	✓	—	—	_____	Lubrication Points				
Body	✓	—	—	_____	Loose Bearings				
Cover	✓	—	—	_____	Guards				
Frame	✓	—	—	_____	Belt Tension				
Dump Mechanism	✓	—	—	_____	Loose Gears				
Steering	✓	—	—	_____	Brakes				
Fire Extinguisher	✓	—	—	_____	Vibration				
Signal System	✓	—	—	_____	Pneu. Interlocks				
Fuel & Gas Lines	✓	—	—	_____	Exhaust System				
Fuel Tank	✓	—	—	_____	Proper RPM				
Exhaust System	✓	—	—	_____	Overload Protect				
Boom	✓	—	—	_____	Mech. Switch				
Boom Hoist	—	—	✓	_____	Ground				
					Continuity				
Sheaves	—	—	✓	_____	Limit Switches				
Hooks,	—	—	✓	_____	Cords				
Grab Bars, Steps	✓	—	—	_____	Plugs/Receptacles				
Warning Lights	✓	—	—	_____					



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/4/19
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓								
Glass	✓								
					Shop Equipment	N/A			
Rear View Mirror	✓				Lubrication Points				
Body	✓				Loose Bearings				
Cover	✓				Guards				
Frame	✓				Belt Tension				
Dump Mechanism			✓		Loose Gears				
Steering	✓				Brakes				
Fire Extinguisher	✓				Vibration				
Signal System	✓				Pneu. Interlocks				
Fuel & Gas Lines	✓				Exhaust System				
Fuel Tank	✓				Proper RPM				
Exhaust System	✓				Overload Protect				
Boom	✓		✓		Mech. Switch				
Boom Hoist			✓		Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/4/14
Equipment Name: MTL w mulcher	Number: 274 High Flow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	—	✓	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	—	✓	—						
Glass	✓	—	—						
Rear View Mirror	—	—	✓		Shop Equipment	N/A			
Body	✓	—	—		Lubrication Points	—	—	—	
Cover	✓	—	—		Loose Bearings	—	—	—	
Frame	✓	—	—		Guards	—	—	—	
Dump Mechanism	—	—	✓		Belt Tension	—	—	—	
Steering	✓	—	—		Loose Gears	—	—	—	
Fire Extinguisher	✓	—	—		Brakes	—	—	—	
Signal System	✓	—	—		Vibration	—	—	—	
Fuel & Gas Lines	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel Tank	✓	—	—		Exhaust System	—	—	—	
Exhaust System	✓	—	—		Proper RPM	—	—	—	
Boom	—	—	✓		Overload Protect	—	—	—	
Boom Hoist	—	—	✓		Mech. Switch	—	—	—	
Sheaves	—	—	✓		Ground	—	—	—	
Hooks,	—	—	✓		Continuity	—	—	—	
Grab Bars, Steps	✓	—	—		Limit Switches	—	—	—	
Warning Lights	✓	—	—		Cords	—	—	—	
					Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/4/14
Equipment Name: MTL w grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓			Getting Worn	Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper		✓							
Glass	✓								
					Shop	N/A			
Rear View Mirror	✓				Equipment				
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom			✓		Overload Protect				
Boom Hoist			✓		Mech. Switch				
Sheaves			✓		Ground				
Hooks,			✓		Continuity				
Grab Bars, Steps	✓				Limit Switches				
Warning Lights	✓				Cords				
					Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/3/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓	—	—		Motor (wiring)	✓	—	—	
Brakes	✓	—	—		Radiator	✓	—	—	
Horn	✓	—	—		Belts	✓	—	—	
Lights	✓	—	—		Hoses	✓	—	—	
Clutch	✓	—	—						
Windshield Wiper	✓	—	—						
Glass	✓	—	—						
					Shop Equipment	N/A			
Rear View Mirror	✓	—	—		Lubrication Points	—	—	—	
Body	✓	—	—		Loose Bearings	—	—	—	
Cover	✓	—	—		Guards	—	—	—	
Frame	✓	—	—		Belt Tension	—	—	—	
Dump Mechanism	✓	—	✓		Loose Gears	—	—	—	
Steering	✓	—	—		Brakes	—	—	—	
Fire Extinguisher	✓	—	—		Vibration	—	—	—	
Signal System	✓	—	—		Pneu. Interlocks	—	—	—	
Fuel & Gas Lines	✓	—	—		Exhaust System	—	—	—	
Fuel Tank	✓	—	—		Proper RPM	—	—	—	
Exhaust System	✓	—	—		Overload Protect	—	—	—	
Boom	✓	—	—		Mech. Switch	—	—	—	
Boom Hoist	—	—	✓		Ground	—	—	—	
Sheaves	—	—	✓		Continuity	—	—	—	
Hooks,	—	—	✓		Limit Switches	—	—	—	
Grab Bars, Steps	✓	—	—		Cords	—	—	—	
Warning Lights	✓	—	—		Plugs/Receptacles	—	—	—	



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/3/14
Equipment Name: MTL - Grapple	Number: 289

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓				Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓							
Glass	✓								
					Shop				N/A
Rear View Mirror	✓				Equipment				
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom			✓		Overload Protect				
Boom Hoist			✓		Mech. Switch				
					Ground				
Sheaves			✓		Continuity				
Hooks,			✓		Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 2/3/14
Equipment Name: MTL ~ mulcher	Number: 279 HighFlow

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	✓				Motor (wiring)	✓			
Brakes	✓				Radiator	✓			
Horn	✓				Belts	✓			
Lights	✓	✓			Hoses	✓			
Clutch	✓								
Windshield Wiper	✓	✓							
Glass	✓								
Rear View Mirror			✓		Shop Equipment	N/A			
Body	✓				Lubrication Points				
Cover	✓				Loose Bearings				
Frame	✓				Guards				
Dump Mechanism			✓		Belt Tension				
Steering	✓				Loose Gears				
Fire Extinguisher	✓				Brakes				
Signal System	✓				Vibration				
Fuel & Gas Lines	✓				Pneu. Interlocks				
Fuel Tank	✓				Exhaust System				
Exhaust System	✓				Proper RPM				
Boom			✓		Overload Protect				
Boom Hoist			✓		Mech. Switch				
					Ground				
Sheaves			✓		Continuity				
Hooks,					Limit Switches				
Grab Bars, Steps	✓				Cords				
Warning Lights	✓				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/3/14
Equipment Name: MTZ ~ mulcher	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop				chainsaw
Rear View Mirror			/		Equipment				
Body	/				Lubrication Points	/			
Cover	/				Loose Bearings			/	
Frame	/				Guards	/			
Dump Mechanism			/		Belt Tension	/			
Steering	/				Loose Gears			/	
Fire Extinguisher	/				Brakes	/			
Signal System	/				Vibration	/			
Fuel & Gas Lines	/				Pneu. Interlocks	/			
Fuel Tank	/				Exhaust System	/			
Exhaust System	/				Proper RPM	/			
Boom			/		Overload Protect	/			
Boom Hoist			/		Mech. Switch	/			
			/		Ground	/			
Sheaves			/		Continuity	/			
Hooks,			/		Limit Switches	/			
Grab Bars, Steps	/				Cords	/			
Warning Lights	/				Plugs/Receptacles	/			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/3/14
Equipment Name: Excavator	Number: 316

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass		/		Cracked					
					Shop Equipment	N/A			
Rear View Mirror	/				Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism	/				Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom	/				Mech. Switch				
Boom Hoist			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/4/14
Equipment Name: MTL - Mulder	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper		/							
Glass	/								
					Shop Equipment	N/A			
Rear View Mirror	/		/		Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism	/				Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom			/		Mech. Switch				
Boom Hoist			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/4/14
Equipment Name: loader	Number: K930

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop				
					Equipment				
Rear View Mirror	/				Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism	/				Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom			/		Mech. Switch				
Boom Hoist			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



OK				BAD				N/A				Remarks			
Tracks, tires, wheels	/							Motor (wiring)	/						
Brakes	/							Radiator	/						
Horn	/							Belts	/						
Lights	/							Hoses	/						
Clutch	/														
Windshield Wiper	/														
Glass	/														
								Shop	N/A						
Rear View Mirror	/							Equipment							
Body	/							Lubrication Points							
Cover	/							Loose Bearings							
Frame	/							Guards							
Dump Mechanism	/							Belt Tension							
Steering	/							Loose Gears							
Fire Extinguisher	/							Brakes							
Signal System	/							Vibration							
Fuel & Gas Lines	/							Pneu. Interlocks							
Fuel Tank	/							Exhaust System							
Exhaust System								Proper RPM							
Boom								Overload Protect							
Boom Hoist								Mech. Switch							
								Ground							
Sheaves								Continuity							
Hooks,								Limit Switches							
Grab Bars, Steps	/							Cords							
Warning Lights	/							Plugs/Receptacles							



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/6/14
Equipment Name: Dump Truck	Number: ~

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop Dump Trailer				
					Equipment				
Rear View Mirror	/				Lubrication Points	/			
Body	/				Loose Bearings			/	
Cover	/				Guards	/			
Frame	/				Belt Tension	/			
Dump Mechanism	/				Loose Gears			/	
Steering	/				Brakes	/			
Fire Extinguisher	/				Vibration	/			
Signal System	/				Pneu. Interlocks	/			
Fuel & Gas Lines	/				Exhaust System	/			
Fuel Tank	/				Proper RPM	/			
Exhaust System	/				Overload Protect	/			
Boom			/		Mech. Switch	/			
Boom Hoist			/		Ground	/			
Sheaves			/		Continuity	/			
Hooks,			/		Limit Switches	/			
Grab Bars, Steps	/				Cords	/			
Warning Lights	/				Plugs/Receptacles	/			



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/6/14
Equipment Name: MTL w grapple	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop				
Rear View Mirror			/		Equipment				
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism	/				Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/		/		Proper RPM				
Boom			/		Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/6/14
Equipment Name: Loader	Number: 930

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop				
Rear View Mirror	/				Equipment	N/A			
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism	/				Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/		/		Proper RPM				
Boom			/		Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/10/14
Equipment Name: Loader	Number: 930

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop Equipment				
Rear View Mirror	/								
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism	/				Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom	/		/		Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/11/14
Equipment Name: MTZ Grapple	Number: 229 - Delivered 3/10/14

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop				N/A
Rear View Mirror	/		/		Equipment				
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism	/				Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom	/		/		Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/11/14
Equipment Name: Loader	Number: 930

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop				
Rear View Mirror	/				Equipment	N/A			
Body	/				Lubrication Points				
Cover	/				Loose Bearings				
Frame	/				Guards				
Dump Mechanism	/				Belt Tension				
Steering	/				Loose Gears				
Fire Extinguisher	/				Brakes				
Signal System	/				Vibration				
Fuel & Gas Lines	/				Pneu. Interlocks				
Fuel Tank	/				Exhaust System				
Exhaust System	/				Proper RPM				
Boom			/		Overload Protect				
Boom Hoist			/		Mech. Switch				
					Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/		X		Cords				
Warning Lights	/		X		Plugs/Receptacles				



OK				BAD				N/A				Remarks			
OK	BAD	N/A	Remarks	OK	BAD	N/A	Remarks								
Tracks, tires, wheels	/			Motor (wiring)	/										
Brakes	/			Radiator	/										
Horn	/			Belts	/										
Lights	/			Hoses	/										
Clutch	/														
Windshield Wiper	/														
Glass	/														
				Shop											
Rear View Mirror		/		Equipment											
Body	/			Lubrication Points											
Cover	/			Loose Bearings											
Frame	/			Guards											
Dump Mechanism	/			Belt Tension											
Steering	/			Loose Gears											
Fire Extinguisher	/			Brakes											
Signal System	/			Vibration											
Fuel & Gas Lines	/			Pneu. Interlocks											
Fuel Tank	/			Exhaust System											
Exhaust System	/			Proper RPM											
Boom		/		Overload Protect											
Boom Hoist		/		Mech. Switch											
				Ground											
Sheaves		/		Continuity											
Hooks,		/		Limit Switches											
Grab Bars, Steps	/			Cords											
Warning Lights	/			Plugs/Receptacles											



OK	BAD	N/A	Remarks	OK	BAD	N/A	Remarks
Tracks, tires, wheels	/			Motor (wiring)	/		
Brakes	/			Radiator	/		
Horn	/			Belts	/		
Lights	/			Hoses	/		
Clutch	/						
Windshield Wiper	/						
Glass	/						
				Shop			
Rear View Mirror	/			Equipment	N/A		
Body	/			Lubrication Points			
Cover	/			Loose Bearings			
Frame	/			Guards			
Dump Mechanism	/			Belt Tension			
Steering	/			Loose Gears			
Fire Extinguisher	/			Brakes			
Signal System	/			Vibration			
Fuel & Gas Lines	/			Pneu. Interlocks			
Fuel Tank	/			Exhaust System			
Exhaust System	/			Proper RPM			
Boom	/			Overload Protect			
Boom Hoist			/	Mech. Switch			
			/	Ground			
Sheaves			/	Continuity			
Hooks,			/	Limit Switches			
Grab Bars, Steps	/			Cords			
Warning Lights	/			Plugs/Receptacles			

[illegible]



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/13/14
Equipment Name: Excavator	Number: 308

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop Equipment	N/A			
Rear View Mirror	/				Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism	/				Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom	/				Mech. Switch				
Boom Hoist			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				



BrightFields, Inc.
Environmental Services

Project Name: Great Kills 2933.01.52	Project Location: Great Kills NY
Inspected by: DJH/JWV	Date of Inspection: 3/14/14
Equipment Name: 172 ✓ Mulcher / Grapple	Number: 279

CONSTRUCTION EQUIPMENT INSPECTION

	OK	BAD	N/A	Remarks		OK	BAD	N/A	Remarks
Tracks, tires, wheels	/				Motor (wiring)	/			
Brakes	/				Radiator	/			
Horn	/				Belts	/			
Lights	/				Hoses	/			
Clutch	/								
Windshield Wiper	/								
Glass	/								
					Shop Equipment	N/A			
Rear View Mirror			/		Lubrication Points				
Body	/				Loose Bearings				
Cover	/				Guards				
Frame	/				Belt Tension				
Dump Mechanism	/				Loose Gears				
Steering	/				Brakes				
Fire Extinguisher	/				Vibration				
Signal System	/				Pneu. Interlocks				
Fuel & Gas Lines	/				Exhaust System				
Fuel Tank	/				Proper RPM				
Exhaust System	/				Overload Protect				
Boom			/		Mech. Switch				
Boom Hoist			/		Ground				
Sheaves			/		Continuity				
Hooks,			/		Limit Switches				
Grab Bars, Steps	/				Cords				
Warning Lights	/				Plugs/Receptacles				