


LNP DEP 6.4-2



Duke Energy Florida
Levy Nuclear Plant
Unit 1 and 2
Part 2, Final Safety Analysis Report

Typical Abnormal Environmental Test
 Profile: Main Control Room
 Figure 3D-201

Rev. 9