



WILLIAM STATES LEE III
NUCLEAR STATION UNITS 1 & 2

PMF Hydrograph With Upper Arm Dam
Failure, Make-Up Pond B

FIGURE 2.4.4-203 Rev 7