



WILLIAM STATES LEE III  
NUCLEAR STATION UNITS 1 & 2

Flood El. Hydrograph Make-Up Pond B  
With Upper Arm Dam Failure,  
72-hr. Local Intense Precipitation

FIGURE 2.4.4-205 Rev 7