

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8707150185 DOC. DATE: 87/07/06 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 DRUCKEMILLER, J. Indiana & Michigan Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 LEEP, T. Michigan, State of

SUBJECT: NPDES noncompliance notification: on 870630, monitoring
 turbine room sump process ph meter found to be inoperative.
 Turbine room sump may have discharged to absorption pond
 during previous 5 hr w/o continuous monitoring.

DISTRIBUTION CODE: IE25D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Environmental Monitoring Rept (per Tech Specs)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-3 LA	1	PD3-3 PD	1
	WIGGINGTON, D	5		
INTERNAL:	AEOD/DOA	1	AEOD/DSP/TPAB	1
	ARM TECH ADV	1	NRR/DEST/ADE	1
	NRR/DREP/RPB	4	REG FILE 02	1
	RES DEPY GI	1	RGN3 FILE 01	1
	RGN2/DRSS/EPRPB	1		
EXTERNAL:	LPDR	1	NRC PDR	1

mencon
lectric
ower

INDIANA & MICHIGAN ELECTRIC COMPANY

ONE SUMMIT SQUARE P O BOX 60, FORT WAYNE, IN. 46801

Telephone (219) 425-2111

July 6, 1987

PRIORITY ROUTING

First	Second
RA	RC
ORA	ETC
ORP	SGZ
ORS	HL
ORSS	OL
ORNA	OI
	PAOI

FILE *lee*

CRIG + 2

Tom Leep, Waste Management Division
Department of Natural Resources
P. O. Box 355
Plainwell, Michigan 49080

RE: Donald C. Cook Nuclear Plant
NPDES Permit No. MI 005827
Groundwater Limitations

Dear Mr. Leep:

This letter confirms my conversation with your office (Laurie) on Friday, July 3 and Monday, July 6, 1987.


At 0740 hours, June 30, the continuously monitoring Turbine Room Sump process pH meter was found to be inoperative in that the recorder pen was stuck in a position indicating a pH of 7.95. A review of the recorder chart and log indicated the the Turbine Room Sump may have discharged to the absorption pond during the previous 5 hours without continuous monitoring of the pH.

While repairs were being made the sump was allowed to empty to the absorption pond only after a grab sample of the effluent was made to verify the pH was within limits. These grab sample values will be so indicated on the monthly DMR for July.

Repairs were completed and the meter returned to normal operation at 2240 hours on July 3, 1987.

By copy of this letter, the Nuclear Regulatory Commission is notified pursuant to the requirements of Appendix B, Part II, Nonradiological, Environmental Protection Plan, Section 3.2.

Very truly yours,



Jack A. Druckemiller
Environmental Affairs Manager

JAD/df

c: W. G. Smith, Jr.

A. B. Davis, NRC, Region III

I certify under penalty of law that I have personally examined and am familiar with the information submitted on this and all attached documents; and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.


Jack A. Druckemiller

8707150185 870706
PDR ADOCK 05000315
S PDR

76-25
1/0

JUL 9 1987

c: M. P. Alexich - Columbus
H. B. Brugger - Columbus
J. E. Dolan - Columbus
R. W. Jurgensen - Columbus
R. F. Kroeger - Columbus
K. D. Mack - Columbus
R. W. Reeves/T. E. Webb/C. E. Hawk - Columbus

A. A. Blind - Cook Plant
T. A. Kriesel/D. Fitzgerald-Stuart - Cook Plant
NRC Resident Inspector - Cook Plant
PNSRC - Cook Plant
J. F. Stietzel - Cook Plant

G. Charnoff, Esq. - Shaw, Pittman, Potts & Trowbridge
R. E. Zahler, Esq. - Shaw, Pittman, Potts & Trowbridge

R. C. Callen - Michigan Public Service Commission

D. R. Hahn - Michigan Department of Public Health

H. R. Denton - Nuclear Reactor Regulations

Dottie Sherman - ANI Library

INPO - Records Center