





**APPENDIX P-6
FSS FIELD LOG**

Survey Area:	LSA-10	Description:	Burial Pit Open Land Area
Survey Unit:	02	Description:	West Central Survey Unit (North Burial Pit Area)

FSS Field Log:

<u>Date/Time:</u>	<u>Observation or Comment:</u>	<u>Technician</u>
1/29/15	<p>Prior to beginning GWS, a task-specific safety briefing was performed by the FSS Supervisor. In the field, before GWS commenced FSS crew confirmed I & C integrity. Background levels were measured at 9.5K - 10K gross cpm. Entered into LSA 10-01 at 1530 and commenced GWS. Weather is partly cloudy and approximately 50° F. No anomalies or foreign debris noted. Exit area at 1710. Files created:</p> <p>LSA_10_02_012915_B_MC LSA_10_02_012915_JW_C</p>	J. Williams 
1/30/15	<p>Prior to beginning GWS, a task-specific safety briefing was performed by the FSS Supervisor. In the field, before GWS commenced FSS crew confirmed I & C integrity. Dewatering performed by ops to allow access to low lying and previously waterlogged areas. Entered into LSA 10-02 at 1015 and GWS performed. Exit area at 1215. Return to area at 1255 to continue GWS. Weather is partly cloudy and approximately 40° F. One of the pits was inaccessible due to extremely soft bottom, even after dewatering. Supervisor notified and corrective actions discussed. Exited area at 1715. Files created:</p> <p>LSA_10_02_013015_B_MC LSA_10_02_013015_B2_MC LSA_10_02_012915_C_JW LSA_10_02_012915_C2_JW</p>	J. Williams 
02/02/15	<p>Prior to beginning GWS, a task-specific safety briefing was performed by the FSS Supervisor. In the field, before GWS commenced FSS crew confirmed I & C integrity. Entered into LSA 10-02 at 0915 to begin filling holes in GWS coverage, including the pit discussed on 1/30/15. Some areas remain inaccessible, but access to them has been discussed with operations. Exit area at 1205. After operations had made the area between the fences accessible, re-enter the area at 1300. Weather is partly cloudy and approximately 30° F. The remainder of the 10-02 GWS area completed and exit area at 1400. Files created:</p> <p>LSA_10_02_020215_C_JW *note that due to the relatively small size, file C2 LSA_10_02_020215_C2_JW was combined into C during post processing LSA_10_02_020215_C3_JW</p>	J. Williams 
02/03/15	<p>Prior to beginning field work, a task-specific safety briefing was performed by the FSS Supervisor. Prior to beginning soil sampling, the FSS crew confirmed I&C integrity. Weather is clear and in the mid 40's. Systematic and Biased Samples collected. Exit area at 1655.</p>	J. Williams 

FSS Field Log 1 of 1