



Tennessee Division of Air Pollution Control (DAPC)

Permits Complaints Inspections eDocuments

SITE or FACILITY INFORMATION

Help

Back to Previous Page

Site Id 7255

Name **Diversified Scientific Services, Inc.**

Description Hazardous waste treatment, storage and disposal facility

Location 657 Gallaher Road

County Roane

Other Counties

City Kingston

Zip 37763

APC Permits at this Site

Permit No	Permittee	Type	Action	Issuance Date	Effective Date	Expiration Date
566728	Diversified Scientific Services, Inc	Title V Renewal	Active	NOV-01-2013	-	OCT-31-2018

1 - 1

Complaints on this Site


no data found

APC Documents on this Site

row(s) 1 - 15 of 52 Next

VIEW	DESCRIPTION	FILE_TYPE	PERMIT_NUMBER	EFFECTIVE_DATE ▼	FACILITY_ID
	Response letter for ACC, January - December 2015 & SAR/MACT report, July - December 2015. Sent by e-mail.	Letter	566728	FEB-11-2016	73-0137
	DSSI ACC January - December 2015	Report	566728	JAN-07-2016	73-0137
	DSSI SAR July - December 2015	Report	566728	JAN-07-2016	73-0137
	Compliance Inspection Annual Title V	Inspection Report	:	OCT-26-2015	73-0137
	Response letter for SAR & MACT report, January - June 2015. Sent by e-mail.	Letter	:	AUG-06-2015	73-0137
	DSSI SAR for January - June 2015	Report	:	JUL-27-2015	73-0137
	SAR/ACC response letter & SER for reports received January 2015.	Letter	:	FEB-02-2015	73-0137
	DSSI ACC Jan 1 - Dec 31, 2014	Report	:	JAN-14-2015	73-0137
	DSSI SAR Jul 1 -				

	Dec 31, 2014	Report	-	JAN-14-2015	73-0137
	Compliance Inspection Annual Title V	Inspection Report	-	DEC-02-2014	73-0137
	APC Acknowledgement of the Comprehensive Performance Test Plan and Continuous Monitoring System Performance Evaluation Plans for 40 CFR 63, Subpart EEE testing for waste fueled boiler system, plans dated July 29, 2014	Source Test Protocol	566728	NOV-14-2014	73-0137
	DSWM acknowledgement of the Comprehensive Performance Test Plan and Continuous Monitoring System Performance Evaluation Plans for 40 CFR 63, Subpart EEE testing for waste fueled boiler system, plans dated July 29, 2014	Source Test Protocol	566728	NOV-07-2014	73-0137
	Response letter for SAR & MACT EEE report January - June 2014	Letter	566728	AUG-11-2014	73-0137
	Comprehensive Performance Test Plan and Continuous Monitoring System Performance Evaluation Plans for 40 CFR 63,	Source Test Protocol	566728	JUL-30-2014	73-0137

Subpart EEE testing for waste fueled boiler system, plans dated July 29, 2014					
	SAR & MACT EEE report January - June 2014	Report	566728	JUL-29-2014	73-0137

row(s) 1 - 15 of 52 **Next** ➤



If you have any questions or comments, Email ask.tdec@tn.gov or call at (888) 891-TDEC (8332).

