

Regulatory

File. Cy



**Consumers
Power
Company**

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

March 10, 1976



Mr James G. Keppler
Office of Inspection Enforcement
Region III
US Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



DOCKET 50-255, LICENSE DPR-20
PALISADES PLANT, ER-76-04
MSIV CLOSING PRESSURE INSTRUMENTATION

Attached is a reportable occurrence which relates to the Palisades Plant. This occurrence has been classified as a reactor protection system or engineered safety feature instrument setting which was found to be less conservative than those established by the Technical Specifications but which do not prevent the fulfillment of the functional requirements of the affected system.

David A. Bixel
Assistant Nuclear Licensing Administrator

2626

MAR 11 1976

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

| | | | |
|---|---|--|---|
| LICENSEE NAME 01 M I P A L 1 | LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0 | LICENSE TYPE 4 1 1 1 1 | EVENT TYPE 0 3 |
| REPORT TYPE 01 CONT | REPORT SOURCE L | DOCKET NUMBER 0 5 0 - 0 2 5 5 | EVENT DATE 0 2 2 1 7 6 |
| REPORT DATE 0 3 1 0 7 6 | | | |

EVENT DESCRIPTION

02 During testing, the MSIV closure set point was found to be below the Technical
03 Specifications limit of "greater than 500 psia" on two instruments. PIC 0751D was
04 found set at 495 psia and PIC 0752A was found at 499 psia."
05 (ER-76-04)
06

| | | | | | |
|---|---|---|---|---|--|
| SYSTEM CODE 07 C D | CAUSE CODE B | COMPONENT CODE I N S T R U | PRIME COMPONENT SUPPLIER N | COMPONENT MANUFACTURER I 1 3 0 | VIOLATION Y |
|---|---|---|---|---|--|

CAUSE DESCRIPTION

08 Instrument set point drift. Set point was adjusted. International Instrument
09 Model No 9223-E
10

| | | | | |
|---|--|---|--|-----------------------------|
| FACILITY STATUS 11 H | % POWER 0 0 0 | OTHER STATUS N | METHOD OF DISCOVERY b | DISCOVERY DESCRIPTION NA |
| FORM OF ACTIVITY RELEASED 12 Z | CONTENT OF RELEASE Z | AMOUNT OF ACTIVITY NA | LOCATION OF RELEASE NA | |

PERSONNEL EXPOSURES

| | | |
|--|---|-------------------|
| NUMBER 13 0 0 0 | TYPE Z | DESCRIPTION NA |
|--|---|-------------------|

PERSONNEL INJURIES

| | |
|--|-------------------|
| NUMBER 14 0 0 0 | DESCRIPTION NA |
|--|-------------------|

PROBABLE CONSEQUENCES

15 Since other set points were satisfactory, proper initiation would have occurred.

LOSS OR DAMAGE TO FACILITY

| | |
|--|-------------------|
| TYPE 16 Z | DESCRIPTION NA |
|--|-------------------|

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19