

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

A. IE Inspection Report No. _____

Transmittal Date : _____

Distribution:
IE Chief, FS&EB
IE:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
IE Files
IE Chief, M&PPB
L:D/D for Reactor Project

B. IE Inquiry Report No. _____

Transmittal Date : _____

Distribution:
IE Chief, FS&EB
IE:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ
DR Central Files
IE Files

C. Incident Notification From: Consumers Power Company 50-255
(Licensee & Docket No. (or License No.))

Transmittal Date : June 16, 1975 Palisades Plant

Distribution:
IE Chief, FS&EB
IE:HQ (4)
Licensing (4)
DR Central Files
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
IE Files



Telegram

VEC289(1452)(1-023322C157)PD 06/06/75 1449

TLX CONSPower JKN

ZCZC 001 DLY JACKSON MICH 6/6/75

PHS USNRC

MR J G KEPPLER

799 ROOSEVELT RD

GLEN ELLYN, IL 60137

LB3
A3312 BOOK NO. 3-20PR. NO. 80

TELEPHONE NBR. 858-2660

TELEPHONED TO JG Keppler BY 43

DATE DLD. 6-6-75 TIME 4:47PM

ATTEMPTS TO DELIVER : mail

50-255

THIS TWX IS TO FOLLOW UP A DISCUSSION WITH MR K R BAKER TODAY CONCERNING A SITUATION AT PALISADES WHICH WE HAVE NOW CLASSIFIED AS ABNORMAL OCCURRENCE 75-12. THE PROBLEM INVOLVES DIFFICULTY IN ADHERING TO TS SECTION 3.9.7 - 3.9.9 WHICH DESCRIBES COOLING TOWER CHLORINATION LIMITATIONS. WE HAVE CONSIDERED CT BLOWDOWN IN THE PAST AS ONLY THAT WHICH IS INTENTIONALLY VALVED OPEN.

SF-1201 (R5-69) WE NOW RECOGNIZE THAT A PORTION OF THE CT PUMP SUCTION BASIN

OVERFLOW IS CT WATER, IN ADDITION TO THE EXPECTED SERVICE WATER. DETAILS WILL FOLLOW IN A FORMAL REPORT LATER.

J G LEWIS

PALISADES PLANT

CONSUMERS POWER COMPANY

CEW

CC: R L HAUETER

R B SEWELL

NNNN