



PEACH BOTTOM ATOMIC POWER STATION
UNITS 2 AND 3
UPDATED FINAL SAFETY ANALYSIS REPORT

Clamps installed on the replacement core spray sparger pipes structurally replacing welds at each of the four sparger T-box locations

FIGURE Q.5.1

REV. 24 04/13