



Metropolitan Edison Company
Post Office Box 542
Reading Pennsylvania 19640
215 929-3601

Writer's Direct Dial Number

July 5, 1979
GQL 0876


Mr. B. H. Grier, Director
Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit 1 (TMI-1)
Operating License No. DPR-50
Docket No. 50-289
LER 79-13/OLT-0

Attached please find the subject event report, which concerns a crack found in the Borated Water Storage Tank suction line. This event is reportable per TMI-1 Technical Specification 6.9.2.A(9).

Sincerely,



J. G. Herbein
Vice President
Generation

JGH:WSS:mrm
Attachment

1002
5/1

7907180 472 S