

ILLINOIS POWER COMPANY



U-0105

L08-79(09-04)-0

500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525

September 4, 1979

Mr. James G. Keppler
Director, Region III
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reference: 1) IE Bulletin No. 79-14, "Seismic Analyses for
As-Built Safety-Related Piping Systems",
July 2, 1979; with Revision 1 of July 18, 1979

Clinton Power Station Units 1 & 2
Docket Nos. 50-461 and 50-462
Construction Permits No. CPPR-137 & CPPR-138

The referenced bulletin requested Illinois Power Company to inspect safety related systems for conformance to seismic analysis input information and to report the results of this inspection within 120 days. The results of such an inspection at Clinton Power Station, if conducted during the specified time frame, would provide little useful information because of the small amount of safety related piping installed to date.

Upon completion of the work, we plan to perform inspections and provide the information requested in the reference in an amendment to the Final Safety Analysis Report for CPS.

Sincerely,

G. E. Wuller
Supervisor - Licensing
Generation Engineering Department

PEW/jh

cc: 1) NRC Director, Office of Inspection & Enforcement
2) NRC Director, Division of Operating Reactors
Office of Nuclear Reactor Regulation

1044 211

7909270806 SEP 6 1979