



# THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

ILLUMINATING BLDG. • PUBLIC SQUARE • CLEVELAND, OHIO 44101 • TELEPHONE (216) 623-1350 • MAIL ADDRESS: P. O. BOX 5000

*Serving The Best Location in the Nation*

Daiwyn R. Davidson

VICE PRESIDENT

SYSTEM ENGINEERING AND CONSTRUCTION

December 20, 1979

Mr. James G. Keppler  
Director of Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

RE: Perry Nuclear Power Plant  
Docket Nos. 50-440; 50-441  
Final Report on  
Inadequate Compaction of  
Class "A" Backfill and  
Settling of Individual Pipes  
of P45 System

Dear Mr. Keppler:

Pursuant to the Interim Report of July 25, 1979, please find attached the Final Report on inadequate compaction of Class "A" backfill around P45 System piping and settling of individual pipes below design elevations.

The attached Final Report includes a description of the deficiency, an analysis of the safety implications, and the corrective action taken, as required by 10CFR50.55(e).

As a result of this Final Report, the condition described herein is no longer considered a Significant Deficiency.

Very truly yours,

D. R. Davidson  
Vice President  
System Engineering and Construction

ksz

Attachment

cc: Victor Stello, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

1678 145

8019  
5/11

8001030 810  
S