

# FEDERAL NOTIFICATION LETTER

Tuesday, March 19, 2019

Director of FSME  
Attn: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

**From General Licensee:**

Divergent 3D  
19601 Hamilton Ave.  
Torrance, CA 90502

**To Specific Licensee:**

SRB Technologies, Inc.  
2580 Landmark Drive  
Winston-Salem, NC 27103  
(336)-659-2610  
Radioactive Materials License #034-0534-2

<b>Date of Transfer:</b> (Enter Date Disposal Box was shipped to Specific Licensee)	
--	--

**Description of Device(s) Transferred:**

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

<b>Printed Name:</b>	
<b>Signature:</b>	
<b>Phone Number:</b>	

**FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT**

VEOLIA USE ONLY

VEOLIA USE ONLY

Sales Order #: 2081896  
Case #: 00025258  
Box 1 of 1

RGA #: 997661  
RGA # Expiration Date: 6/15/19  
UCN: 1A51389B-6C55095D  
FedEx Tracking #: 691191700755461

### TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	K9299	101	K9299	Shield Source	7.5
2.	K9297	101	K9297	Shield Source	7.5
3.	K9306	101	K9306	Shield Source	7.5
4.	K9300	101	K9300	Shield Source	7.5

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

NONE

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

#### GENERATOR CERTIFICATION

Generator Signature:

Sandy NunezTitle: Account Manager

Print Name:

Sandy NunezDate: 3/11/2019

#### VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received:

3-11-19

Checked in by:

Angie Kung