

Franklin Medical Consultants
Southfield, MI

December 28, 2019

Ms Laura Cender
U.S. Nuclear Regulatory Commission
Division of Nuclear Materials Safety
Region III
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352


Dear Ms Cender:

This letter is in response to your email of December 11, 2019 requesting additional information the termination request for license no. 21-12460-01.

1. The radioisotopes used at the site are:
 - a. Tc-99m last used 10/8/2019
 - b. I-123 last used 1/28/2019
 - c. I-131 last used 2/12/2019
 - d. Tl-201 not used in the last 3 years
2. A revised diagram is attached.
3. All areas were tested using one wipe. The count of that wipe was performed using a well counter. The procedure is to use one wipe of all areas. If that wipe passes the testing it is complete. If that wipe does not pass, then all areas are wiped separately to determine where the contamination is and then clean it up. It is then retested.

If there are any questions please call me at 734-395-7361 cell.

Sincerely,


Ray A. Carlson, MS
Medical Physicist

RECEIVED DEC 30 2019

5007H FIELD, MI. 48038


Handwritten: $Y \sim N(\mu, \sigma^2)$

↑
~

LAB

Exam
Room

U 510510



OFFICE

HOT LAB CONTAINS

1. DOSE CALIBRATION
WELL COUNTER

SHIELDED STORAGE FOR SOURCES AND WASTE