

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	A	D	A	C	1	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	1	4	5															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35															
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE										CAT 58									

0	1	L	6	0	5	0	0	0	3	3	1	7	0	6	1	6	8	1	3	0	7	1	5	8	1	9													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35											
REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During surveillance testing, drywell equipment drain line (Containment Isolation) valve CV-3729 did not give a fully closed indication. Tech. Spec. 3.7.D lists the containment isolation valve operability requirements. The redundant isolation valve was operable. The Rx was shutdown at the time this problem was discovered and CV-3729 was repaired and tested sat. prior to plant startup. No similar previous occurrences concerning valve CV-3729 have been reported.

0	9	M	A	11	E	12	B	13	V	A	L	V	O	P	14	E	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE							
17		18		19		20		21		22		23		24		25		26	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD	
8		1		0		2		4		0		3		L		0		Z	
33		34		35		36		37		38		39		40		41		42	
C		Z		Z		Z		0		0		0		0		N		N	
43		44		45		46		47		48		49		50		51		52	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											
10		23		24		25		26											
Isolation valve CV-3729 nonclosure was caused by seat leakage in solenoid valve SV-3729. Foreign material on the SV-3729 seat resulted in air leakage through SV-3729 to the CV-3729 piston drive. The solenoid valve was replaced and CV-3729 was retested satisfactorily. The solenoid valve is an ASCO Model NP831665E. No further corrective action planned.		41		42		43		44											

Isolation valve CV-3729 nonclosure was caused by seat leakage in solenoid valve SV-3729. Foreign material on the SV-3729 seat resulted in air leakage through SV-3729 to the CV-3729 piston drive. The solenoid valve was replaced and CV-3729 was retested satisfactorily. The solenoid valve is an ASCO Model NP831665E. No further corrective action planned.

1	5	G	28	0	0	0	29	NA	B	31	Surveillance Testing	32
7	8	9	10	11	12	13	14	15	16	17	18	19
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
30		31		32		33		34				
15		16		17		18		19				
Z		Z		NA		NA		NA				
35		36		37		38		39				
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION		39				
40		41		42		43		44				
0		0		0		NA		NA				
45		46		47		48		49				
PERSONNEL INJURIES		NUMBER		DESCRIPTION		41		42				
50		51		52		53		54				
0		0		0		NA		NA				
55		56		57		58		59				
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		43		44				
60		61		62		63		64				
Z		NA		NA		NA		NA				
65		66		67		68		69				
PUBICITY		ISSUED		DESCRIPTION		45		46				
70		71		72		73		74				
N		NA		NA		NA		NA				
75		76		77		78		79				
8107240156		810715		PDR		ADOCK		05000331				
80		81		82		83		84				
PDR		PDR		PDR		PDR		PDR				
85		86		87		88		89				
90		91		92		93		94				
95		96		97		98		99				
100		101		102		103		104				
105		106		107		108		109				
110		111		112		113		114				
115		116		117		118		119				
120		121		122		123		124				
125		126		127		128		129				
130		131		132		133		134				
135		136		137		138		139				
140		141		142		143		144				
145		146		147		148		149				
150		151		152		153		154				
155		156		157		158		159				
160		161		162		163		164				
165		166		167		168		169				
170		171		172		173		174				
175		176		177		178		179				
180		181		182		183		184				
185		186		187		188		189				
190		191		192		193		194				
195		196		197		198		199				
200		201		202		203		204				
205		206		207		208		209				
210		211		212		213		214				
215		216		217		218		219				
220		221		222		223		224				
225		226		227		228		229				
230		231		232		233		234				
235		236		237		238		239				
240		241		242		243		244				
245		246		247		248		249				
250		251		252		253		254				
255		256		257		258		259				
260		261		262		263		264				
265		266		267		268		269				
270		271		272		273		274				
275		276		277		278		279				
280		281		282		283		284				
285		286		287		288		289				
290		291		292		293		294				
295		296		297		298		299				
300		301		302		303		304				
305		306		307		308		309				
310		311		312		313		314				
315		316		317		318		319				
320		321		322		323		324				
325		326		327		328		329				
330		331		332		333		334				
335		336		337		338		339				
340		341		342		343		344				
345		346		347		348		349				
350		351		352		353		354				
355		356		357		358		359				
360		361		362		363		364				
365		366		367		368		369				
370		371		372		373		374				
375		376		377		378		379				
380		381		382		383		384				
385		386		387		388		389				
390		391		392		393		394				
395		396		397		398		399				
400		401		402		403		404				
405		406		407		408		409				
410		411		412		413		414				
415		416		417		418		419				
420		421		422		423		424				
425		426		427		428		429				
430		431		432		433		434				
435		436		437		438		439				
440		441		442		443		444				
445		446		447		448		449				
450		451		452		453		454				
455		456		457		458		459				
460		461		462		463		464				
465		466		467		468		469				
470		471		472		473		474				
475		476		477		478		479				
480		481		482		483		484				
485		486		487		488		489				
490		491		492		493		494				
495		496		497		498		499				
500		501		502		503		504				
505		506		507		508		509				
510		511		512		513		514				
515		516		517		518		519				
520		521		522		523		524				
525		526		527		528		529				
530		531		532		533		534				
535		536		537		538		539				
540		541		542		543		544				
545		546		547		548		549				
550		551		552		553		554				
555		556		557		558		559				
560		561		562		563		564				
565		566		567		568		569				
570		571		572		573		574				
575		576		577		578		579				
580		581		582		583		584				
585		586		587		588		589				
590		591		592		593		594				
595		596		597		598		599				
600		601		602		603		604				
605		606		607		608		609				
610		611		612		613		614				
615		616		617		618		619				
620		621		622		623		624				
625		626		627		628		629				
630		631		632		633		634				
635		636		637		638		639				
640		641		642		643		644				
645		646		647		648		649				
650		651		652		653		654				
655		656		657		658		659				
660		661		662		663		664				
665		666		667		668		669				
670		671		672		673		674				
675		676		677		678		679				
680		681		682		683		684				
685		686		687		688		689				
690		691		692		693		694				
695		696		697		698		699				
700		701		702		703		704				
705		706		707		708		709				
710		711		712		713		714				
715		716		717		718		719				
720		721		722		723		724				
725		726		727		728		729				
730		731		732		733		734				
735		736		737		738		739				
740		741		742		743		744				
745		746		747		748		749				
750		751		752		753		754				
755		756		757		758		759				
760		761		762		763		764				
765		766		767		768		769				
770		771		772		773		774				
775		776		777		778		779				
780		781										