

CONTROL BLOCK: 

						1
--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	7	7	0	6	0	8	8	1	8	0	7	0	8	8	1	9
60	61									68	69						74	75						80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

0 2 | At 0815, during normal operation, the Containment Radiation Monitoring  
0 3 | System (RMS) pump failed resulting in a loss of the Containment gaseous  
0 4 | and particulate radiation monitor (T.S. 3.4.6.1). The redundant RMS  
0 5 | pump was immediately started and flow restored to the gaseous monitor.  
0 6 | The particulate monitor was returned to service at 1310. The contain-  
0 7 | ment sump level alarm system remained operable during this event. LER  
0 8 | 80-46 (U-1) describes a similar occurrence.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
		B	B	E	F	P	U	M	P	X	X	G	Z				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
21	22	23	24	25	26	27	28	29	30	31	32						
17	8	1	—	0	4	9	—	0	3	L	—	0					
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			
C	Z	Z	Z	0	0	0	0	N	N	A	C	5	2	1			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The sample pump seized during operation and was removed from service.

1 1 It was replaced with a spare. It appears that the graphite pump vanes

1 2 bound up and broke off causing seizure. This is a normal end of life

1 3 failure. We are investigating a Preventive Maintenance Program and

1 4 the replacement of Conde Pumps.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	28	1	0	0	29	NA	A	31	Operator Observation			

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z 33 Z 34 NA

7 8 9 10 11 14

LOCATION OF RELEASE (36)

NA

45 48 50

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	40 NA

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
1 9 Z (42) NA  
7 8 9 10 8107240248 810708

ISSUED DESCRIPTION (45) PDR AD0CK 05000317 PDR NRC USE ONLY

NAME OF PREPARER J. S. Lagiewski/C.L. Rayburn

PHONE (301) 269-4747/4803