

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO CAT

CONT

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

While in Mode 4, performance of a daily routine checklist revealed that the air temperature - Delta T meteorological monitoring strip chart recorder was not functioning properly, and was subsequently declared inoperable. This violates T.S. 3.3.3.4 which is reportable per T.S. 6.9.1.13(b). Since there were no radioactive gaseous waste releases made while the recorder was inoperative, in addition to operation of the redundant data logger and magnetic tape recorder, the health and safety of the public were not affected.

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE C.J.M.P. SLACODE VALVE SUBCODE

LER/RD REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO.

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The strip chart recorder (Tracer Westronics, Model M11E) failed due to the shaft of the inkwheel assembly (part No. A27672) binding with the inkwell bushing (part No. A27671), causing the pointer to chatter and remain at one point. The shaft and bushing were replaced, and the ambient temperature and Delta T instrumentation loops were calibrated per procedure.

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

PERSONNEL INJURIES NUMBER DESCRIPTION

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

PUBLICITY ISSUED DESCRIPTION

NRC USE ONLY

NAME OF PREPARER Phillip B. Nardoci PHONE: (704) 373-7432

8108130122 810804
PDR ADOCK 05000369
S PDR