

GP4 2512

-USS-09 SPR-107 -

SHAW-WALKER
Toll Call # 85008



CONFIDENTIAL
COUNSEL ONLY

8307080721 750715
PDR ADDCK 05000289
S HOL

2024

0 2 4 1

50-287

THE BABCOCK & WILCOX COMPANY
POWER GENERATION GROUP

To | Distribution

From G. K. Wandling, Technical Support (2451)

BOS 663.5

Cust. DPC, Met Ed, FPC, APSL, SMUD, TECO

File No.
or Ref. NSS-9 SPR-107

Subj. Electromatic Relief Valve Malfunction

Date
July 15, 1975

This letter is cover and customer and one subject only.

Distribution

L. C. Rogers
E. L. Logan
J. A. Bailey
C. E. Mitchell
R. J. Baker
C. A. Creacy

Reference: 620-0009 SPR-107 "Electromatic Relief Valve Malfunction" -
Attached

The attached SPR documents a problem which resulted from corrosion of the lever pin, lever hinge and solenoid bracket of the subject valve.

Please advise your customer to conduct periodic inspections for presence of corrosion products and to perform manual/visual checks for freedom of motion during plant shutdowns.

C. A. Creacy is requested to verify with Duke that they intend to adopt a surveillance inspection program on this valve for all three units.

GKW/cs

cc: J. T. Janis
K. R. Ellison
R. A. Govers
J. D. Phinney
F. G. Grisbaum
R. G. Burnley
J. P. Kennedy

05/30 06/16 11/29
SITE INSTRUCTION NO. 07/24, 11/21, 3/24/76
DISTRIBUTION ABOVE
NSS-3, 4, 5, 7, 8, 9, 11, 14
RESPONSE REQUESTED FROM
APPROVED *[Signature]*

2024 0247