



SONGS RADIOLOGICAL SURVEY



DATE 06/02/2014


TIME 0715

Page 1 of 1

UNIT	N	SURVEY REASON <input type="checkbox"/> Routine <input type="checkbox"/> Job Coverage <input type="checkbox"/> Pwr Entry ____% <input type="checkbox"/> Post-Decon <input type="checkbox"/> Shipment/Receipt <input type="checkbox"/> Source/Leak Test <input checked="" type="checkbox"/> Other Confirmatory Surveys	SURVEY NO.	190602-002
AREA	YD		MO NO.	N/A
ELEV	N/A		REP NO.	
ROOM	G-20		EQUIP. ID.	

Denotes floor area scanned with floor monitor.

MESA- G20 WAREHOUSE



Floor Monitor BKG.=40cps

2-1 BKG.=40-60cpm

No detectable counts above BKG. during floor scans.

Survey points 1-10 were on the floor and 11-20 were taken on the interior walls.
with no detectable counts above BKG.

SMEARS						MASSLINNS		
NO.	β - γ	α	NO.	β - γ	α	NO.	Gross dpm	Hot Part. (Y/N)
1	<1K	N/A	16	<1K	N/A	A	N/A	N
2			17			B		
3			18			C		
4			19			D		
5			20	<1K		E		
6			21	N/A		F		
7			22					
8			23					
9			24					
10			25					
11								
12								
13								
14								
15	<1K	N/A		N/A	N/A	N/A	N/A	N

SURVEY CLASS ☐ Trend Pt. ☐ Component
☐ Boundary ☒ General Area ☐ Individual

SURVEY DESCRIPTION: Mesa Confirmatory Survey

REMARKS: All accessible floor area scanned using the floor monitors. All survey points consist of direct frisk readings and 100cm2 smears.

No floor drains were present in the building.

Instruments used

Model	FLM3B	FLM3B	2-1	N/A	N/A
Serial No.	01	02	271981		

TECHNICIAN		SURVEY TYPE
Print	J.Papson/M.Crimes	<input type="checkbox"/> Shutdown (S/D)
Sign		Reference Number
APPROVED BY		SO123-VII-20.9
Print		Form Number
Sign		SCE HP (2/3) 1259-1000
Approval	Date: 6-24-14 Time: 1130	REV. 3 09/07