

# SONGS MESA



# SONGS RADIOLOGICAL SURVEY


DATE 05 / 27 / 2014TIME 0745Page 1 of 1

UNIT	N	SURVEY REASON <input type="checkbox"/> Routine <input type="checkbox"/> Job Coverage <input type="checkbox"/> Pwr Entry % <input checked="" type="checkbox"/> Other Confirmatory Surveys	<input type="checkbox"/> Post-Decon	<input type="checkbox"/> Pre-Job
AREA	YD		<input type="checkbox"/> Shipment/Receipt	
ELEV	N/A		<input type="checkbox"/> Source/Leak Test	
ROOM	G-48			

SURVEY NO.	<u>140527-003</u>
MO NO.	<u>N/A</u>
REP NO.	
EQUIP. ID.	

Floor Monitor BKG.=37cps  
2-1 BKG.=60cpm

G-48 Classroom 105



SMEARS						MASSLINNS		
NO.	$\beta$ - $\gamma$	$\alpha$	NO.	$\beta$ - $\gamma$	$\alpha$	NO.	Gross dpm	Hot Part. (Y/N)
1	<1K	N/A	16	<1K	N/A	A	N/A	N
2			17	N/A		B		
3			18			C		
4			19			D		
5			20			E		
6			21			F		
7			22					
8			23					
9			24					
10			25					
11								
12								
13								
14								
15	<1K	N/A		N/A	N/A		N/A	N

SURVEY CLASS ☐ Trend Pt. ☐ Component  
☐ Boundary ☒ General Area ☐ Individual

SURVEY DESCRIPTION: Mesa Confirmatory Surveys

REMARKS: All accessible floor area scanned with the floor monitors. All survey points consist of direct frisk readings and 100 cm<sup>2</sup> smears. No detectable counts above background detected. Survey points 1-10 taken on the floor and 11-16 taken on the interior walls.

No floor drains located in room.

## Instruments used

Model	FLM3B	FLM3B	2-1	N/A	N/A
Serial No.	01	02	271981		

## TECHNICIAN

Print B.Dynes/M.Crumes/J.Papson

Sign *B.Dynes*

## APPROVED BY

Print *Carey*

Sign *Carey*

Approval Date: 6/24/14 Time: 1120

## SURVEY TYPE

☐ Shutdown (S/D)

Reference Number  
SO123-VII-20.9

Form Number

SCE HP (2/3) 1259-1000  
REV. 3 09/07