



SONGS RADIOLOGICAL SURVEY



DATE 3/11/14

TIME 1600

Page 1 of 1

UNIT	MESA	SURVEY REASON	<input type="checkbox"/> Post-Decon	<input type="checkbox"/> Pre-Job
AREA	Yard	<input type="checkbox"/> Routine	<input type="checkbox"/> Shipment/Receipt	
ELEV	30'	<input type="checkbox"/> Job Coverage	<input type="checkbox"/> Source/Leak Test	
ROOM	N/A	<input type="checkbox"/> Pwr Entry %	<input checked="" type="checkbox"/> Other Tool Inspection	

SURVEY NO.	140311-602
MO NO.	A0106140001
REP NO.	200278-5
EQUIP. ID.	

SMEARS						MASSLINNS		
NO.	β - γ	α	NO.	β - γ	α	NO.	Gross dpm	Hot Part. (Y/N)
1			16			A	<1K	N
2			17			B	<1K	N
3			18			C	<1K	N
4			19			D	<1K	N
5			20			E	<1K	N
6			21			F	<1K	N
7			22			G	<1K	N
8			23			H	<1K	N
9			24			I	<1K	N
10			25			J	<1K	N
11						K	<1K	N
12						L	<1K	N
13						M	<1K	N
14						N	<1K	N
15						O	<1K	N

SURVEY CLASS	<input type="checkbox"/> Trend Pt.	<input checked="" type="checkbox"/> Component
<input type="checkbox"/> Boundary	<input checked="" type="checkbox"/> General Area	<input type="checkbox"/> Individual

SURVEY DESCRIPTION: Tool Inspection at the MESA for action

REMARKS:

Instruments used			
Model	SPA-8	2-1	
Serial No.	1877	258976	N

TECHNICIAN		SURVEY TYPE
Print	Robb Haskins	<input type="checkbox"/> Shutdown (S/D)
Sign	Robb Haskins	Reference Number
APPROVED BY		SO123-VII-20.9
Print		Form Number
Sign		SCE HP (2/3) 1259-1000
Approval	Date:	REV. 3 09/07
	Time:	

Tool Inspection at MESA Buildings

BLD. # G-44 masslinns A, B, C.

BLD. # G-46 masslinns D, E, F.

BLD. # G-47 masslinns G, H, I.

BLD. # G-49 masslinns J, K, L.

Big white tent. masslinns M, N, O.

ALL item <1K Fixed And <1K smearable.

they did not HAVE any magenta paint on them.

BACK Ground For the SPA-8 was 1500 cpm.

no tools were ABOVE BACK Ground.

ALL masslinns SMEARS were <1K dpm/100cm²

I did about 10% of the tools in the Buildings.