



SONGS RADIOLOGICAL SURVEY


 DATE 3/13/14

 TIME 1500

 Page 1 of 1

UNIT	MESA	SURVEY REASON <input type="checkbox"/> Routine <input type="checkbox"/> Job Coverage <input type="checkbox"/> Pwr Entry % <input checked="" type="checkbox"/> Other <u>Tool Inspection</u>	<input type="checkbox"/> Post-Decon <input type="checkbox"/> Shipment/Receipt <input type="checkbox"/> Source/Leak Test <input checked="" type="checkbox"/> Other
AREA	YARD		
ELEV	30'		
ROOM			

SURVEY NO.	140313-001
MO NO.	A0106140001
REP NO.	200278-5
EQUIP. ID.	

SMEARS						MASSLINNS		
NO.	β - γ	α	NO.	β - γ	α	NO.	Gross dpm	Hot Part (Y/N)
1			16			A	<1K	N
2			17			B	<1K	N
3			18			C	<1K	N
4			19			D	<1K	N
5			20			E	<1K	N
6			21			F	<1K	N
7			22			G	<1K	N
8			23			H	<1K	N
9			24			I	<1K	N
10			25			J	<1K	N
11						K	<1K	N
12						L	<1K	N
13						M	<1K	N
14						N	<1K	N
15						O	<1K	N

Tool Inspection at MESA Buildings
 Bld. # G-20 masslinns A, B, C.
 Bld. # G-21 masslinns D, E, F.
 Bld. # G-30 masslinns G, H, I.
 Bld. # G-40 masslinns J, K, L.
 Bld. # W-44 masslinns M, N.
 Bld. # W-43 masslinn O.

ALL items < 1K Fixed and < 1K smearable.
 They did not have any magenta paint on them.

Background for the SPA-8 was 1500 cpm,
 no tools were above background.

ALL MASSLINNS SMEARS were < 1K dpm/
 I did about 10% of the tools in the buildings.

SURVEY CLASS	<input type="checkbox"/> Trend Pt.	<input type="checkbox"/> Component
<input type="checkbox"/> Boundary	<input checked="" type="checkbox"/> General Area	<input type="checkbox"/> Individual

SURVEY DESCRIPTION: Tool Inspection
at the MESA for action

REMARKS:

Instruments used

Model	SPA-8	2-1		
Serial No.	1877	258979		N

TECHNICIAN		SURVEY TYPE
Print	Robb Haskins	<input type="checkbox"/> Shutdown (S/D)
Sign	Robb Haskins	Reference Number
APPROVED BY		SO123-VII-20.9
Print		Form Number
Sign		SCE HP (2/3) 1259-1000
Approval	Date:	REV. 3 09/07
	Time:	