

# The Light company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483


March 31, 1993  
ST-HL-AE-4395  
File No.: T07.03  
10CFR50

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

South Texas Project Electric Generating Station  
Unit 1  
Docket No. STN 50-498  
Unit 1 Fourth Refueling Outage Inservice  
Inspection Summary Report for System Pressure Tests

Enclosed is the Unit 1 fourth refueling outage (1RE04) Inservice Inspection Summary Report for System Pressure Tests performed under the ASME Code, Section XI at the South Texas Project Electric Generating Station. This Summary Report includes the period from completion of the third refueling outage (April 4, 1991) to completion of the fourth refueling outage (December 31, 1992).

If you should have any questions on this matter, please contact Mr. A. W. Harrison at (512) 972-7298.

  
S. L. Rosen  
Vice President,  
Nuclear Engineering

HRP/pla

Attachments: Per Attached Index

RREP\93089002.U2

Project Manager on Behalf of the Participants in the South Texas Project

9304130317 930407  
PDR ADDCK 05000498  
Q PDR