

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

8204160267 820407
PDR ADCK 05000247
S PDR

NA

68 69 80

ATTACHMENT I

Docket No. 05000247
LER #: 82-011/03L-0

Consolidated Edison
Indian Point Station, Unit 2

Specifications - Safety Valve 1828

MFG: Crosby Valve And Gage Co.
SIZE: 2"
MODEL: RV52JWS
CROSBY DWG #: H-51048

Corrective Actions (Continued)

In order to prevent recurrence, the BIT sampling frequency has been increased until repairs to safety valve 1828 have been completed.