

The Light company

Houston Lighting & Power

South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

May 14, 1993
ST-HL-AE-4448
File No.: T07.03
10CFR50


U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 1
Docket No. STN 50-498
Unit 1 Fourth Refueling Outage Inservice
Inspection Summary Report for Repairs and Replacements
Addendum 1

Reference: ST-HL-AE-4396, Inspection Summary Report for
Repairs and Replacements, dated March 31, 1993.

Enclosed is the Unit 1 fourth refueling outage (1RE04)
Inservice Inspection Summary Report for Repairs and Replacements
Addendum 1, performed under the ASME Code, Section XI at the South
Texas Project Electric Generating Station. This Summary Report
Addendum includes the period from completion of the third refueling
outage (April 4, 1991) to completion of the fourth refueling outage
(December 31, 1992). The attachment completes the Inspection
Summary Report for Repairs and Replacements, referenced above.

If you should have any questions on this matter, please
contact Mr. H. R. Pate at (512) 972-7787.


S. L. Rosen
Vice President,
Nuclear Engineering

HRP/sr

180052

Attachment: Unit 1 Fourth Refueling Outage Inservice Inspection
Summary Report for Repairs and Replacements,
Addendum 1.

RREP\93131001.U1

Project Manager on Behalf of the Participants in the South Texas Project

9305190301 930514
PDR ADDCK 05000498
Q PDR

AC47

Houston Lighting & Power Company
South Texas Project Electric Generating Station

ST-HL-AE-4448
File No.: T07.03
Page 2

C:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

Lawrence E. Kokajko
Project Manager
U.S. Nuclear Regulatory Commission
Washington, DC 20555 13H15

J. I. Tapia
Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C., STE 1000
1615 L Street, N.W.
Washington, DC 20036

D. E. Ward/T. M. Puckett
Central Power and Light Company
P. O. Box 2121
Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

K. J. Fiedler/M. T. Hardt
City Public Service
P. O. Box 1771
San Antonio, TX 78296

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61867
Houston, TX 77208

Institute of Nuclear Power
Operations - Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

D. K. Lackner
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

U.S. Nuclear Regulatory Comm.
Attn: Document Control Desk
Washington, D.C. 20555

INDEX OF ATTACHMENTS

1. Cover Sheet
2. 1RE04 Inservice Inspection Summary Report for Repairs and Replacements,
Addendum - 1