

# LICENSEE EVENT REPORT

Palisades

[PLEASE PRINT ALL REQUIRED INFORMATION]

CONTROL BLOCK:                  

|  |  |   |  |
|--|--|---|--|
| <p>LICENSEE NAME</p> <p><span style="border: 1px solid black; padding: 0 5px;">01</span> <span style="border: 1px solid black; padding: 0 5px;">M</span> <span style="border: 1px solid black; padding: 0 5px;">I</span> <span style="border: 1px solid black; padding: 0 5px;">P</span> <span style="border: 1px solid black; padding: 0 5px;">A</span> <span style="border: 1px solid black; padding: 0 5px;">L</span> <span style="border: 1px solid black; padding: 0 5px;">L</span> <span style="border: 1px solid black; padding: 0 5px;">1</span></p> | <p>LICENSE NUMBER</p> <p><span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">-</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">-</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span></p> | <p>LICENSE TYPE</p> <p><span style="border: 1px solid black; padding: 0 5px;">4</span> <span style="border: 1px solid black; padding: 0 5px;">1</span> <span style="border: 1px solid black; padding: 0 5px;">1</span> <span style="border: 1px solid black; padding: 0 5px;">1</span> <span style="border: 1px solid black; padding: 0 5px;">1</span></p>  | <p>EVENT TYPE</p> <p><span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">3</span></p>   |
| <p>REPORT TYPE</p> <p><span style="border: 1px solid black; padding: 0 5px;">01</span> CONT</p>  | <p>REPORT SOURCE</p> <p><span style="border: 1px solid black; padding: 0 5px;">L</span></p>  | <p>DOCKET NUMBER</p> <p><span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">5</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">-</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">2</span> <span style="border: 1px solid black; padding: 0 5px;">5</span> <span style="border: 1px solid black; padding: 0 5px;">5</span></p> | <p>EVENT DATE</p> <p><span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">4</span> <span style="border: 1px solid black; padding: 0 5px;">2</span> <span style="border: 1px solid black; padding: 0 5px;">1</span> <span style="border: 1px solid black; padding: 0 5px;">7</span> <span style="border: 1px solid black; padding: 0 5px;">6</span></p> |
| <p>REPORT DATE</p> <p><span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">5</span> <span style="border: 1px solid black; padding: 0 5px;">2</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">7</span> <span style="border: 1px solid black; padding: 0 5px;">6</span></p>  |  |   |  |

## EVENT DESCRIPTION

02 During testing (RO-8, Loss of Off-Site Power/SIS Test) the charging pump (P55-A)

03 failed to perform properly. Analysis of the test results disclosed that the pump

04 started and ran for 10 seconds before shutting down. The standby pump (P55-B)

05 started following trip of P55-A and provided the necessary capacity.

06 (ER-76-10)

|  |   |   |   |   |   |
|--|---|---|---|---|---|
| SYSTEM CODE  | CAUSE CODE  | COMPONENT CODE  | PRIME COMPONENT SUPPLIER  | COMPONENT MANUFACTURER  | VIOLATION   |
| <span style="border: 1px solid black; padding: 0 5px;">07</span> <span style="border: 1px solid black; padding: 0 5px;">R</span> <span style="border: 1px solid black; padding: 0 5px;">B</span> | <span style="border: 1px solid black; padding: 0 5px;">A</span> | <span style="border: 1px solid black; padding: 0 5px;">F</span> <span style="border: 1px solid black; padding: 0 5px;">I</span> <span style="border: 1px solid black; padding: 0 5px;">L</span> <span style="border: 1px solid black; padding: 0 5px;">T</span> <span style="border: 1px solid black; padding: 0 5px;">E</span> <span style="border: 1px solid black; padding: 0 5px;">R</span> | <span style="border: 1px solid black; padding: 0 5px;">N</span> | <span style="border: 1px solid black; padding: 0 5px;">M</span> <span style="border: 1px solid black; padding: 0 5px;">O</span> <span style="border: 1px solid black; padding: 0 5px;">7</span> <span style="border: 1px solid black; padding: 0 5px;">5</span> | <span style="border: 1px solid black; padding: 0 5px;">Y</span> |

## CAUSE DESCRIPTION

08 The pump trip resulted from a plugged oil filter. This filter has been changed

09 and the pump operates satisfactorily. This filter change requirement is on our

10 preventative maintenance schedule. However, this maintenance was delayed for

|  |   |              |   |                       |
|--|---|--------------|---|-----------------------|
| FACILITY STATUS  | % POWER   | OTHER STATUS | METHOD OF DISCOVERY   | DISCOVERY DESCRIPTION |
| <span style="border: 1px solid black; padding: 0 5px;">11</span> <span style="border: 1px solid black; padding: 0 5px;">G</span> | <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> | NA           | <span style="border: 1px solid black; padding: 0 5px;">b</span> | NA                    |

|  |   |                    |                     |
|--|---|--------------------|---------------------|
| FORM OF ACTIVITY RELEASED  | CONTENT OF RELEASE  | AMOUNT OF ACTIVITY | LOCATION OF RELEASE |
| <span style="border: 1px solid black; padding: 0 5px;">12</span> <span style="border: 1px solid black; padding: 0 5px;">Z</span> | <span style="border: 1px solid black; padding: 0 5px;">Z</span> | NA                 | NA                  |

## PERSONNEL EXPOSURES

|  |   |             |
|--|---|-------------|
| NUMBER   | TYPE  | DESCRIPTION |
| <span style="border: 1px solid black; padding: 0 5px;">13</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> | <span style="border: 1px solid black; padding: 0 5px;">Z</span> | NA          |

## PERSONNEL INJURIES

|  |             |
|--|-------------|
| NUMBER   | DESCRIPTION |
| <span style="border: 1px solid black; padding: 0 5px;">14</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> <span style="border: 1px solid black; padding: 0 5px;">0</span> | NA          |

## PROBABLE CONSEQUENCES

15 None - Redundant equipment available.

## LOSS OR DAMAGE TO FACILITY

|  |             |
|--|-------------|
| TYPE   | DESCRIPTION |
| <span style="border: 1px solid black; padding: 0 5px;">16</span> <span style="border: 1px solid black; padding: 0 5px;">Z</span> | NA          |

## PUBLICITY

17 NA

## ADDITIONAL FACTORS

18 about four months due to the refueling outage. The necessity of adhering to PM

19 work will be reviewed with the maintenance supervisors.


8308150368 760520  
PDR ADOCK 05000255  
S PDR



Consumers  
Power  
Company

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

May 20, 1976



Mr James G. Keppler  
Office of Inspection Enforcement  
Region III  
US Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

DOCKET 50-255, LICENSE DPR-20 -  
PALISADES PLANT - ER-76-10 -  
CHARGING PUMP P55-A

Attached is a reportable occurrence which relates to the Palisades Plant.  
This occurrence has been classified as a thirty-day reportable event.

*David A. Bixel*

David A. Bixel  
Assistant Nuclear Licensing Administrator

COPY SENT REGION ~~III~~

5498

MAY 23 1976