


A-26 3/8/64

FIGURE 11



DOCKETED  
USNRC  
MAR 19 1964  
OFFICE OF SECRETARY  
DOCKETING & SERVICE  
BRANCH

LUMBERK GEN. NATING STATION  
UNITS 1 AND 2  
FINAL SAFETY ANALYSIS REPORT  
INTENSE STORM SITE RUMOFF  
PATTERN: SPRAY POND AND  
COOLING TOWER AREAS

FIGURE 2-48

8405230538 840308  
PDR ADOCK 05000352  
PDR

U. S. NUCLEAR REGULATORY COMMISSION

EXHIBIT No. 26  
Applicant ☒ Staff ☐ Intervenor  
Identified ☒ Received ☒ Rejected  
Date: 3/8/84  
Reporter: M. M. [Signature]

PROD. & UTIL. DIV. **50-3522/353**