

# OhioEPA DISCHARGE MONITORING REPORT

## COMMENTS:

PERMITTEE NAME Toledo Edison Company  
 ADDRESS Davis-Besse Nuclear Power Station  
 5501 North State Route 2  
 PHONE Oak Harbor, Ohio 43449  
 (419) 259-5000

(2-3) OH ST	(4-16) 21B00011 PERMIT NUMBER	(17-19) 001 DIS	(20-21)(22-23)(24-25) 814016011 YEAR MO DAY	(26-27)(28-29)(30-31) 814016310 YEAR MO DAY
		SIC	W 83° 5' N 41° 35' LATITUDE LONGITUDE	

REPORTING PERIOD FROM

TO

TO

(32-37)

(1 card only) (4 card only)

(64-66)

(68-70)

PARAMETER		QUANTITY				CONCENTRATION				FREQUENCY OF ANALYSIS	SAMPLE TYPE
		(38-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	(62-63) UNITS	(38-45) MINIMUM	(46-53) MAXIMUM	(54-61) AVERAGE	(62-63) UNITS		
00011 Water Temperature	REPORTED	64	75	87	°F					1/1	CONT
	PERMIT CONDITION										
00400 pH	REPORTED					7.5	8.6		pH	1/1	GRAB
	PERMIT CONDITION					6.0	9.0		S.U.		
50050 Conduit Flow	REPORTED	5.3	20.3	27.8	MGD					CONT.	24 hour Total
	PERMIT CONDITION										
50060 Total Residual Chlorine	REPORTED					0.0	0.0	0.0	mg/l	1/1	GRAB
	PERMIT CONDITION										
50064 Free Available Chlorine	REPORTED					0.0	0.0	0.0	mg/l	1/1	GRAB
	PERMIT CONDITION						0.5	0.2			
	REPORTED										
	PERMIT CONDITION										
	REPORTED										
	PERMIT CONDITION										
	REPORTED										
	PERMIT CONDITION										

8407230027 840630  
 PDR ADOCK 05000346  
 R PDR

NAME OF PRINCIPAL EXECUTIVE OFFICER			TITLE OF THE OFFICER			DATE		
CROUSE,	RICHARD	P.	VICE PRES/NUCLEAR	814	07015			
LAST	FIRST	MI	TITLE	YEAR	MO DAY			

I certify that I am familiar with the information contained in this report and that to the best of my knowledge and belief such information is true, complete, and accurate.

SIGNATURE OF PRINCIPLE EXECUTIVE OFFICER OR AUTHORIZED AGENT

# Ohio EPA DISCHARGE MONITORING REPORT

## COMMENTS:

PERMITTEE NAME: Toledo Edison Company  
 ADDRESS: Davis-Besse Nuclear Power Station  
 5501 North State Route 2  
 PHONE: Oak Harbor, Ohio 43449  
 (419) 259-5000

Total Nonfilterable Residue (Total Suspended Solids)  
 daily maximum limit of 50 mg/l was exceeded June 4, 1984.  
 Report was issued to Ohio EPA on June 6, 1984.

(2-3) OH -1	(4-16) 21B00011 PERMIT NUMBER	(17-19) 002 DIS	(20-21)(22-23)(24-25) 814 016 011 YEAR MO DAY	(26-27)(28-29)(30-31) 814 016 310 YEAR MO DAY
			TO	
			(3 card only) (4 card only)	

(32-37)		(3 card only) (4 card only)										(64-66)	(68-70)	
PARAMETER		QUANTITY				CONCENTRATION				FREQUENCY OF ANALYSIS	SAMPLE TYPE			
		(38-45)	(46-53)	(54-61)	(62-63)	(38-45)	(46-53)	(54-61)	(62-63)					
00400 pH	REPORTED						8.0	8.2		pH	0	1/7	GRAB	
	PERMIT CONDITION						6.0	9.0		S.U.				
00530 Total nonfilterable Residue	REPORTED						22	63	39	mg/l	1	1/7	GRAB	
	PERMIT CONDITION							50						
50050 Conduit Flow	REPORTED	0.000	0.031	0.428	MGD							CONT	24 hour Total	
	PERMIT CONDITION													
	REPORTED													
	PERMIT CONDITION													
	REPORTED													
	PERMIT CONDITION													
	REPORTED													
	PERMIT CONDITION													
	REPORTED													
	PERMIT CONDITION													
	REPORTED													
	PERMIT CONDITION													
NAME OF PRINCIPAL EXECUTIVE OFFICER		TITLE OF THE OFFICER			DATE		I certify that I am familiar with the information contained in this report and that to the best of my knowledge and belief such information is true, complete, and accurate.					SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT		
CROUSE, RICHARD P.	VICE PRES./NUCLEAR	8 4 0 7 0 5												
LAST	FIRST	MI	TITLE			YEAR	MO	DAY						

# OhioEPA DISCHARGE MONITORING REPORT

## COMMENTS:


PERMITTEE NAME Toledo Edison Company  
 ADDRESS Davis-Besse Nuclear Power Station  
 5501 North State Route 2  
 PHONE Oak Harbor, Ohio 43449  
 (419) 259-5000

(2-3) OH ST	(4-16) 21B00011 PERMIT NUMBER	(17-19) 003 DIS	SIC	(26-27)(28-29)(30-31) W 83° 5' N 41° 35' LATITUDE LONGITUDE
REPORTING PERIOD FROM		(20-21)(22-23)(24-25) 8 4 0 6 0 1 YEAR MO DAY	TO (26-27)(28-29)(30-31) 8 4 0 6 3 1 0 YEAR MO DAY	

(32-37) PARAMETER		(38-45) QUANTITY (54-61)				(46-53) CONCENTRATION (54-61)					(62-63) UNITS	(64-66) FREQUENCY OF ANALYSIS	(68-70) SAMPLE TYPE
		(38-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	(54-61) UNITS	(38-45) MINIMUM	(46-53) MAXIMUM	(54-61) AVERAGE					
50050 Conduit Flow	REPORTED	0.222	0.222	0.222	MGD							CONT	24 hour Total
	PERMIT CONDITION												
00530 Total nonfilterable Residue	REPORTED					58	58	58	mg/l		1/30	GRAB	
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												

NAME OF PRINCIPAL EXECUTIVE OFFICER		TITLE OF THE OFFICER		DATE	
CROUSE,	RICHARD	P. VICE PRES/NUCLEAR		8 4 0 7 0 5	
LAST	FIRST	MI	TITLE	YEAR	MO DAY

I certify that I am familiar with the information contained in this report and that to the best of my knowledge and belief such information is true, complete, and accurate.

  
 SIGNATURE OF PRINCIPLE EXECUTIVE  
 OFFICER OR AUTHORIZED AGENT

# OhioEPA DISCHARGE MONITORING REPORT

## COMMENTS:

PERMITTEE NAME: Toledo Edison Company  
 ADDRESS: Davis-Besse Nuclear Power Station  
 5501 North State Route 2  
 Oak Harbor, Ohio 43449  
 PHONE: (419) 259-5000

(2-3) OH ST	(4-16) 21B00011 PERMIT NUMBER	(17-19) 601 DIS	(20-21)(22-23)(24-25) 814 016 011 YEAR MO DAY	(26-27)(28-29)(30-31) 814 016 310 YEAR MO DAY
		(SIC)	(29-31) W 83° 5' LATITUDE	(32-34) N 41° 35' LONGITUDE

(32-37)		(3 card only) (4 card only)										(64-66)		(68-70)	
PARAMETER		QUANTITY				UNITS	QUALIFICATION				FREQUENCY OF ANALYSIS	SAMPLE TYPE			
		(18-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	(62-63) MINIMUM		(46-53) MAXIMUM	(54-61) AVERAGE	(62-63) UNITS						
00083 Color	REPORTED						0	1	1	Severity Units		1/1	GRAB		
	PERMIT CONDITION														
01330 Odor	REPORTED						0	0	0	Severity Units		1/1	GRAB		
	PERMIT CONDITION														
01350 Turbidity	REPORTED						0	1	1	Severity Units		1/1	GRAB		
	PERMIT CONDITION														
50050 Conduit Flow	REPORTED	0.009	0.009	0.009	MCD		0.2	3.0	1.8			CONT	24 hour Total		
	PERMIT CONDITION														
50060 Total Residual Chlorine	REPORTED									mg/l		1/1	GRAB		
	PERMIT CONDITION														
00310 BOD (5-day)	REPORTED						10	10	10	mg/l	0	1/30	GRAB		
	PERMIT CONDITION							45	30						
00400 pH	REPORTED						9.1	9.1		pH	0	1/30	GRAB		
	PERMIT CONDITION						6.0	10.0		S.U.					
00530 Total nonfilterable Residue	REPORTED						19	19	19	mg/l	0	1/30	GRAB		
	PERMIT CONDITION							45	30						
NAME OF PERSONAL MONITOR		TITLE OF PERSONAL MONITOR				SIGNATURE OF PERSONAL MONITOR				DATE					
CROUSE RICHARD P.		VICE PRES/NUCLEAR				814 017 015				YBMurray					
LAST FIRST MI		TITLE				I certify that the information reported on this report and furnished to the best of my knowledge and belief such information is true, complete, and accurate.				OFFICER OR AUTHORIZED AGENT					


# OhioEPA DISCHARGE MONITORING REPORT

## COMMENTS:

PERMITTEE NAME Toledo Edison Company  
 ADDRESS Davis-Besse Nuclear Power Station  
 5501 North State Route 2  
 PHONE Oak Harbor, Ohio 43449  
 (419) 229-5000

(2-3) OH ST	(4-16) 21B00011 PERMIT NUMBER	(17-19) 601 DIS	SIC	W 83° 5' LATITUDE	N 41° 35' LONGITUDE
REPORTING PERIOD FROM		TO			
(20-21)(22-23)(24-25) 8 14 0 16 0 11 YEAR MO DAY		(26-27)(28-29)(30-31) 8 14 0 16 3 10 YEAR MO DAY			

PARAMETER		QUANTITY				UNITS	CONCENTRATION				FREQUENCY OF ANALYSIS	SAMPLE TYPE
		(38-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	(62-63) UNITS		(38-45) MINIMUM	(46-53) MAXIMUM	(54-61) AVERAGE	(62-63) UNITS		
31616 Fecal Coliform (MF-FCB)	REPORTED	97	97	97	No/100	0				1/30	GRAB	
	PERMIT CONDITION		200	400	ml							
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											

NAME OF PRINCIPAL EXECUTIVE OFFICER	TITLE OF THE OFFICER	DATE	I certify that I am familiar with the information contained in this report and that to the best of my knowledge and belief such information is true, complete, and accurate.	 SIGNATURE OF PRINCIPLE EXECUTIVE OFFICER OR AUTHORIZED AGENT
CROUSE, RICHARD P.	VICE PRES/NUCLEAR	8 14 0 17 0 15 YEAR MO DAY		

# OhioEPA DISCHARGE MONITORING REPORT

PERMITTEE NAME Toledo Edison Company  
 ADDRESS Davis-Besse Nuclear Power Station  
 5501 North State Route 2  
 PHONE Oak Harbor, Ohio 43449  
 (419) 259-5000

COMMENTS:

(2-3) OH ST	(4-16) 21B00011 PERMIT NUMBER	(17-19) 602 DIS	SIC	(26-27)(28-29)(30-31) W 83° 5' N 41° 35' LATITUDE LONGITUDE
REPORTING PERIOD FROM		TO		
(20-21)(22-23)(24-25) 8 14 0 16 0 11 YEAR MO DAY		(26-27)(28-29)(30-31) 8 14 0 16 3 10 YEAR MO DAY		

(32-37)		(38-45) (46-53) QUANTITY (54-61)				(62-63) (38-45) (46-53) CONCENTRATION (54-61)				(64-66) (68-70)	
PARAMETER		MINIMUM	AVERAGE	MAXIMUM	UNITS	MINIMUM	MAXIMUM	AVERAGE	UNITS	FREQUENCY OF ANALYSIS	SAMPLE TYPE
00400 pH	REPORTED					8.0	8.4		pH	0	GRAB
	PERMIT CONDITION					6.0	10.5		S.U.		
00530 Total Nonfilterable Residue	REPORTED					2	12	7		0	GRAB
	PERMIT CONDITION						100	30	mg/l		
00550 Total oil & grease	REPORTED					0	0	0		0	GRAB
	PERMIT CONDITION						20	15	mg/l		
50050 Conduit Flow	REPORTED	0.136	0.136	0.136	MCD					CONT	24 hour total
	PERMIT CONDITION										
	REPORTED										
	PERMIT CONDITION										
	REPORTED										
	PERMIT CONDITION										
	REPORTED										
	PERMIT CONDITION										
	REPORTED										
	PERMIT CONDITION										
NAME OF PRINCIPAL EXECUTIVE OFFICER		TITLE OF THE OFFICER		DATE		I certify that I am familiar with the information contained in this report and that to the best of my knowledge and belief such information is true, complete, and accurate.				SIGNATURE OF PRINCIPLE EXECUTIVE OFFICER OR AUTHORIZED AGENT	
COURSE,	RICHARD P.	VICE PRES/NUCLEAR		8	4						
LAST	FIRST	TITLE		YEAR	MO						

## DISCHARGE MONITORING REPORT

PERMITTEE NAME

Toledo Edison Company

ADDRESS

## Davis-Besse Nuclear Power Station

PHONE

5501 North State Route 2

Oak Harbor, Ohio 43449

(419) 259-5000

**COMMENTS:**

Neutralizing tank out of service for repair during the entire month of June.

(2-3)	(4-16)	(17-19)		
OH	21B00011	603		W 83° 5'
ST	PERMIT NUMBER	DIS	SIC	N 41° 35'
				LATITUDE LONGITUDE
		(20-21)(22-23)(24-25)		(26-27)(28-29)(30-31)
	REPORTING PERIOD	FROM		TO
		8   4   0   6   0   1		8   4   0   6   3   0
		YEAR MD DAY		YEAR MD DAY

(32-37)			(3 card only) (4 card only)										(64-66)		(68-70)	
PARAMETER		QUANTITY					CONCENTRATION					FREQUENCY OF ANALYSIS	SAMPLE TYPE			
		(38-45)	(46-53)	(54-61)	(62-63)	(38-45)	(46-53)	(54-61)	(62-63)							
		MINIMUM	AVERAGE	MAXIMUM	UNITS	<input type="checkbox"/>	MINIMUM	MAXIMUM	AVERAGE	UNITS	<input type="checkbox"/>					
00400 pH	REPORTED					<input type="checkbox"/>	AH	AH	AH	pH	<input type="checkbox"/>	Each discharge	GRAB			
	PERMIT CONDITION					<input type="checkbox"/>	6.0	9.0			S.U.	<input type="checkbox"/>				
00530 Total nonfilterable residue	REPORTED					<input type="checkbox"/>	AH	AH	AH	mg/l	<input type="checkbox"/>	Each discharge	GRAB			
	PERMIT CONDITION					<input type="checkbox"/>		100	30			<input type="checkbox"/>				
50050 Conduit flow	REPORTED	0.000	0.000	0.000	MGD	<input type="checkbox"/>					<input type="checkbox"/>	Each discharge	24 hour total			
	PERMIT CONDITION					<input type="checkbox"/>						<input type="checkbox"/>				
	REPORTED					<input type="checkbox"/>					<input type="checkbox"/>					
	PERMIT CONDITION					<input type="checkbox"/>						<input type="checkbox"/>				
	REPORTED					<input type="checkbox"/>					<input type="checkbox"/>					
	PERMIT CONDITION					<input type="checkbox"/>						<input type="checkbox"/>				
	REPORTED					<input type="checkbox"/>					<input type="checkbox"/>					
	PERMIT CONDITION					<input type="checkbox"/>						<input type="checkbox"/>				
	REPORTED					<input type="checkbox"/>					<input type="checkbox"/>					
	PERMIT CONDITION					<input type="checkbox"/>						<input type="checkbox"/>				
	REPORTED					<input type="checkbox"/>					<input type="checkbox"/>					
	PERMIT CONDITION					<input type="checkbox"/>						<input type="checkbox"/>				
	REPORTED					<input type="checkbox"/>					<input type="checkbox"/>					
	PERMIT CONDITION					<input type="checkbox"/>						<input type="checkbox"/>				
	REPORTED					<input type="checkbox"/>					<input type="checkbox"/>					
	PERMIT CONDITION					<input type="checkbox"/>						<input type="checkbox"/>				

NAME OF PRINCIPAL EXECUTIVE OFFICER

CROUSE, RICHARD P

LAST FIRST MI

TITLE OF THE OFFICER

VICE PRES/NUCLEAR


TITLE

DATE

8/4/07

YEAR MO DAY

I certify that I am familiar with the information contained in this report and that to the best of my knowledge and belief such information is true, complete, and accurate.



SIGNATURE OF PRINCIPLE EXECUTIVE OFFICER OR AUTHORIZED AGENT

# OhioEPA DISCHARGE MONITORING REPORT

## COMMENTS:

PERMITTEE NAME Toledo Edison Company  
 ADDRESS Davis-Besse Nuclear Power Station  
 5501 North State Route 2  
 PHONE Oak Harbor, Ohio 43449  
 (419) 259-5000

(2-3) OH ST	(4-16) 2IB00011 PERMIT NUMBER	(17-19) 604 DIS	SIC	(20-21)(22-23)(24-25) 814 016 01 YEAR MO DAY	(26-27)(28-29)(30-31) 814 016 310 YEAR MO DAY
		W 83° 5' N 41° 35' LATITUDE LONGITUDE			

(32-37)		(3 card only) (4 card only)										(64-66)	(68-70)
PARAMETER		(38-45)	(46-53)	(54-61)	(62-63)	(38-45)	(46-53)	(54-61)	(62-63)	(38-45)	(46-53)	(64-66)	(68-70)
		MINIMUM	AVERAGE	MAXIMUM	UNITS	MINIMUM	MAXIMUM	AVERAGE	UNITS	MINIMUM	MAXIMUM	FREQUENCY OF ANALYSIS	SAMPLE TYPE
00400 pH	REPORTED					8.0	8.2		pH			1/7	GRAB
	PERMIT CONDITION					6.0	9.0		S.U.				
00550 Total oil & grease	REPORTED					0	0	0	mg/l			1/7	GRAB
	PERMIT CONDITION						20	15					
50050 Conduit Flow	REPORTED	0.106	0.106	0.106	MCD							CONT	24 hour Total
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
	REPORTED												
	PERMIT CONDITION												
NAME OF PRINCIPAL EXECUTIVE OFFICER		TITLE OF THE OFFICER			DATE		I certify that I am familiar with the information contained in this report and that to the best of my knowledge and belief such information is true, complete, and accurate.					SIGNATURE OF PRINCIPLE EXECUTIVE OFFICER OR AUTHORIZED AGENT	
CROUSE,	RICHARD	P.	VICE PRES/NUCLEAR			814 017 015							
LAST	FIRST	MI	TITLE			YEAR MO DAY							


# OhioEPA DISCHARGE MONITORING REPORT

## COMMENTS:

PERMITTEE NAME Toledo Edison Company  
 ADDRESS Davis-Besse Nuclear Power Station  
 5501 North State Route 2  
 PHONE Oak Harbor, Ohio 43449  
 (419) 259-5000

(2-3) OH ST	(4-16) 21B00011 PERMIT NUMBER	(17-19) 801 DIS	SIC	W 83° 5' LATITUDE	N 41° 35' LONGITUDE
REPORTING PERIOD FROM		TO			
(20-21)(22-23)(24-25) 8 14 0 16 0 11 YEAR MO DAY		(26-27)(28-29)(30-31) 8 14 0 16 3 10 YEAR MO DAY			

PARAMETER		QUANTITY				CONCENTRATION					FREQUENCY OF ANALYSIS	SAMPLE TYPE
		(38-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	(62-63) UNITS	(64-66) MINIMUM	(67-68) MAXIMUM	(69-70) AVERAGE	(71-72) UNITS			
00011 Water Temperature	REPORTED	57	68	72	°F						1/1	CONT
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											
	REPORTED											
	PERMIT CONDITION											

NAME OF PRINCIPAL EXECUTIVE OFFICER	TITLE OF THE OFFICER	DATE	I certify that I am familiar with the information contained in this report and that to the best of my knowledge and belief such information is true, complete, and accurate.	 SIGNATURE OF PRINCIPLE EXECUTIVE OFFICER OR AUTHORIZED AGENT
CROUSE, RICHARD P.	VICE PRES/NUCLEAR	8 14 0 7 0 15 YEAR MO DAY		



File: RR 2-P-12-84-06  
E 2.40.1.1.2  
G84 405AL

July 11, 1984

Ohio Environmental Protection Agency  
Technical Records Section  
P.O. Box 1049  
Columbus, Ohio 43216

Gentlemen:

Attached is a copy of the June 1984 Ohio EPA Discharge Monitoring Report  
for Davis-Besse Nuclear Power Station.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station  
(419) 259-5660

TDM/KLN/yml  
encl.

cc: J. E. Sullivan  
W. G. Rogers, U.S. NRC Resident Inspector  
J. L. Scott-Wasilk  
J. F. Stolz, NRC

IE 25  
1/1