

RE-113

## FIELD INSPECTION REPORT

3. RECORD CONTROL

CONTROL NO. C-63FILE NO. JM-1-45-121. PROJECT NO. 9931 2. DATE 10/26/76 PAGE 1 OF 14. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED  
THE FOLLOWING O.C.T. INSPECTION PLANS: C109 W1-4  
C192 W1-9 C201 W1-7 C201 W1-105. LOCATION REACTOR #2 ELV 253' AREA 13-176. TYPE OF INSPECTION VISUAL & DIMENSIONAL7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D1.1 72 R1-73 R2-74  
C91-1 W1-9 2/0 C63-1 PART 1-5-76 PART 2 C109 W1-4  
C192 W1-9 C201 W1-7 C201 W1-10  
NCR 19808. INSPECTION EQUIPMENT USED FILLET WELD GAGE9. RESULTS OF INSPECTION: SATISFACTORY ☒ UNSATISFACTORY ☐

10. ACTION TAKEN IF UNSATISFACTORY

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED. ALSO SEE  
OCG1-1 REPORT NOS. C-63-3 DATED 10-27-76 AND  
C-63-14 DATED 11-2-76. MODIFIED  
ALSO FOR RE-INSPECTION - SEE REPORT C-63-22 DATED 4-5-77  
MODIFIED 7-2

Distribution:  
White - CC Files  
Canary - Originator

K. B. B. B.

11. ENGINEER

11/11/76