

RECEIVED

## FIELD INSPECTION REPORT

 3 RECORD CONTROL  
 CONTROL NO. C-63-  
 FILE NO. PK-1-C-1-

1. PROJECT NO. 9031 2. DATE 10/25/76 PAGE OF

 4. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED ON  
 THE FOLLOWING O.C.T. INSPECTION PLANS C199 W1-1-  
 C199 W1-17 C195 W1-17

5. LOCATION REACTOR #2 ELV 217 AREA 17, 15

6. TYPE OF INSPECTION VISUAL + DIMENSIONAL

 7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D.1-1.22 P1.23 P2.24  
 C91/W1-17 C63.1 ADOT 1-1 P1/2  
 C199 W1-13 C195 W1-17 C199 W1-17  
 NCR #1980

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

 9. RESULTS OF INSPECTION: SATISFACTORY ☐ UNSATISFACTORY ☒

 10. ACTION TAKEN IF UNSATISFACTORY NCR 1998 WAS GENERATED DUE TO  
 UNACCEPTABLE WELDS COVERED ON O.C.T.R. C199 W1-

 NOTE - FOR RE-INSPECTIONS ACCOMPLISHED - ALSO  
 SEE OLCI-1 REPORT # C-63-22 DATED 4-5-77. CHADIN  
 7-25

 Distribution:  
 White - GC Files  
 Canary - Originator

K.B. L.P.

11. ENGINEER

J. J. H. H. H.