

RE-USE

## FIELD INSPECTION REPORT

3 RECORD CONTROL

CONTROL NO. 6-63-1

FILE NO. 22-11-49

1. PROJECT NO. 5031 2. DATE 10/29/72 PAGE 1 OF 14. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED  
THE FOLLOWING OCT INSPECTION PLANS C 197 W 1-10  
C 197 W 1-9A C 197 W 1-115. LOCATION REACTOR #1 ELV 217 229A 11 15 + 166. TYPE OF INSPECTION VISUAL + DIMENSIONAL7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION RWS 01-1-72 R-173 R2-74  
C 9112 W 9 2/2 C 63-1 PART 1-5 PART 2  
C 197 W 1-10 C 197 W 1-9A C 197 W 1-11 NCR 19508. INSPECTION EQUIPMENT USED FILLET WELD GAGE9. RESULTS OF INSPECTION: SATISFACTORY ☒ UNSATISFACTORY ☐

10. ACTION TAKEN IF UNSATISFACTORY

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED ALSO  
SEE REPORT # 063-22 DATED 4-5-77 CRD Line 7-28Distribution:  
White - CC Files  
Canary - OriginatorL. B. B. B.11. ENGINEER L. B. B. B.