



FIELD INSPECTION REPORT

3. RECORD CONTROL

CONTROL NO. C-63-12

FILE NO. EPC-45-3-12


1. PROJECT NO. 8031 2. DATE 11/1/76 PAGE ____ OF ____

4. ITEM INSPECTED PARTIAL RE-INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING P.I.C.T. INSPECTION PLANS.

C201 W1-5 C204 W1-2

5. LOCATION REACTOR #2 ELV 253 + 2.93 AREA 13 + 14

6. TYPE OF INSPECTION VISUAL & DIMENSIONAL

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D1.1-73 REV 1-73 REV 2-74
C91 REV 6 WQ 2/0 C63 REV 1 ADDIT 1-5, FA'2
C201 W1-5 C204 W1-2 NCR 1980

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY ☒ UNSATISFACTORY ☐

10. ACTION TAKEN IF UNSATISFACTORY

B411270224 B40507
PDR ADCK 05000352
Q PDR

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED ALSO SEE OCGI-1 REPORT NOS. C-63-28 DATED 7-1-77 AND C-63-29 DATED 7-1-77. MODIFIED 7-28-77 ALSO SEE REPORT C-63-22 DATED 4-5-77

DISTRIBUTION
Where - QC Files
Where - Inspector

K. Bishop 11-1-76

11. ENGINEER

V. J. Waters