



APPL. EX. 77
FIELD INSPECTION REPORT

REF: 31

GEN. CCL

1. RECORD CONTROL

CONTROL NO. C-63-24

FILE NO. SP-1-63-23


1. PROJECT NO. 8031

2. DATE 7/5/77

PAGE 1 OF 1

4. ITEM INSPECTED Re-inspection of walls in quarters in Quarters, Central Inspection Plan P-192-11-1-10. Bridges to rooms and bridges to outside fill walls, beams 1A29 and 1A36 and 1A21-14-5

5. LOCATION Reactor Unit #1 FBR 701'



MR-1990

6. TYPE OF INSPECTION Visual & Dimensional

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D1.1-72, P1-73, E2-74
NFI Inspection Plan P-192-11-1-10 C-63/2 1A21-3 FA2
Dug P-192/14

8. INSPECTION EQUIPMENT USED Fillet width gage & wire brush

9. RESULTS OF INSPECTION: SATISFACTORY ☒ UNSATISFACTORY ☐

10. ACTION TAKEN IF UNSATISFACTORY

8411270351 840507
PDR ADOCK 05000352
G PDR

NOTE: FOR INSPECTIONS PREVIOUSLY ACCOMPLISHED.
ALSO SEE OGGI-1 REPORT # C-63-13 DATED 12-29-70.
ALSO FOR PREVIOUS INSPECTIONS SEE REPORT C-63-22 DATED 4-5-77

REBUL

11. ENGINEER Fred H. Lush