KEF:36 GEN. OCBC

FIELD INSPECTION REPORT

APPL. EX. 82

3. RECORD CONTROL
CONTROL NO. C-6-3-29
FILE NO. [illegible]

1. PROJECT NO. 6031 2. DATE 7/1/77 PAGE 1 OF 1

4. ITEM INSPECTED Re-inspection of welds in question in Quality control inspection plan C-201-W-1-5. Angles to beams and angles to column fillet welds, beam No. 233B1 to column 109C2

DOCKETED
AUG 1984
DOCKETING & SERVICE BRANCH
SECY-NRC

NCL-1980

5. LOCATION Reactor Unit #2 Elev. 253'

6. TYPE OF INSPECTION Visual & Dimensional

7. STANDARD/CODE/PROCEDURE/DRAWING/SPECIFICATION AWS D1.1-72, R1-73, R2-74
QCI Inspection Plan C-201-W-1-5 C-63/2 Add 1-3 Rev
Dwg C-201/5

8. INSPECTION EQUIPMENT USED Fillet weld gage, wire brush & Inspection mirror

9. RESULTS OF INSPECTION: SATISFACTORY ☑ UNSATISFACTORY ☐

10. ACTION TAKEN IF UNSATISFACTORY

8411270365 840507
PDR ADOCK 05000352
G PDR

NOTE: FOR INSPECTIONS PREVIOUSLY ACCOMPLISHED
ALSO SEE QCG1-1 REPORT # C-63-12 dated 11-1-76.
ALSO SEE REPORT # C-63-22 dated 4-5-77

[signature]
7-28-77

Distribution:
White — QC Files
Canary — Originator

[signature]
7-11-77

11. ENGINEER Carl H. Turley