



GPU Nuclear Corporation
Post Office Box 480
Route 441 South
Middletown, Pennsylvania 17057-0191
717 944-7621
TELEX 84-2386
Writer's Direct Dial Number
(717) 948-8005

September 14, 1992
C311-92-2123

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Dear Sir:

Subject: Three Mile Island Nuclear Station, Unit 1 (TMI-1)
Operating License No. DPR-50
Do let No. 50-289
First Half - 1992 Semiannual Effluent Release Report

Enclosed is the TMI-1 Semiannual Effluent Release Report for the period January 1, 1992 through June 30, 1992. This report includes an Executive Summary of the Effluent Release Report, the Disposal and Effluent Release Data, and an assessment of the radiation doses due to liquid and gaseous effluents released from the unit during the reporting period.

TMI-1 Technical Specification Sections 6.9.4.2.1 and 6.9.4.2.2 require reporting of effluent and solid waste shipment data in accordance with Reg. Guide 1.21 for the semi-annual report period. These tables are attached and include summaries of solid waste shipments and liquid and gaseous effluents for the reporting period.

TMI-1 Technical Specification Section 6.9.4.2.3 requires a summary of unplanned releases from the site to unrestricted areas. During this report period there were no unplanned releases.

TMI-1 Technical Specification Section 6.9.4.2.4 requires that changes to the Process Control Program (PCP) and Offsite Dose Calculation Manual (ODCM) be reported. The ODCM was revised during this report period and submitted to the NRC via GPU Nuclear letter C311-92-2076 dated June 11, 1992. This letter is included as Attachment 1. The PCP was not revised. Section 6.9.4.2.4 also requires "a listing of new locations for dose calculations and/or monitoring identified by the land use census pursuant to Specification 3.23.2." There were no new locations identified during this semiannual period.

170032

9209210194 920914
PDR ADOCK 05000289
R PDR

GPU Nuclear Corporation is a subsidiary of General Public Utilities Corporation

JE48

TMI-1 Technical Specification Section 6.9.4.2.5 requires reporting of instrumentation not returned to OPERABLE status within 30 days per Section 3.21.1.b and 3.21.2.b. All such instrumentation was maintained operable or returned to OPERABLE service within 30 days.

Sincerely,



T. G. Broughton
Vice President and Director, TMI-1

JSS/mkk

Enclosures

cc: Administrator Region I
TMI-1 Senior Project Manager
TMI Senior Resident Inspector