



City Engineering Department
Ninth Floor Cadillac Tower
Detroit, Michigan 48226

Coleman A. Young, Mayor
City of Detroit

March 11, 1985

United States
Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attention: Mr. Bill Reichhold

Dear Sir,

Enclosed are the subject drawings discussed in telephone conversation
of March 11, 1985.

8506100714 850517
REG3 LIC30
21-24406-01 PDR

James T. Crane

James T. Crane, P. E.
Resident Engineer

RECEIVED

MAR 13 1985


REGION III

MAR 13 1985


1-23-85
Rlt

NUCLEAR GAUGE STORAGE AREA

City Engineering Department
Southfield Yard Field Office
12255 Southfield Road Detroit, MI 48228
SOUTHFIELD YARD



DETAIL OF OFFICE AREA




NUCLEAR ROOM IS
LOCKED AND CAUTION
SIGN POSTED

Storage Area: Room Size 12'w x 14' d
Type of Materials Stored: Troxler Nuclear Density Gauges.
How Stored? In Manufacturer's Cases on Floor.
Rooms Adjacent? Hallway
Office.
Motor Pool Garage.


Elmer McFarland 935-3828
Art Van Heese 224-3915

NUCLEAR GAUGE STORAGE AREA

City Engineering Department
Southfield Yard Field Office
12255 Southfield Road Detroit, MI 48228
SOUTHFIELD YARD



DETAIL OF OFFICE AREA



NUCLEAR ROOM IS
LOCKED AND CAUTION
SIGN POSTED

Storage Area: Room Size 12'w x 14' d
Type of Materials Stored: Troxler Nuclear Density Gauges.
How Stored? In Manufacturer's Cases on Floor.
Rooms Adjacent? Hallway
Office.
Motor Pool Garage.

Elmer McFarland 935-3828
Art Van Heese 224-3915

CONVERSATION RECORD

TIME 11:11 AM

DATE 1/10/85

TYPE

☐ VISIT

☐ CONFERENCE

☒ TELEPHONE

☐ INCOMING

☒ OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

ORGANIZATION (Office, dept., bureau, etc.)

TELEPHONE NO.

MIKE KANARZ

CITY OF DETROIT ENGINEERING

(313) 935-3353

SUBJECT

INFORMATION NEEDED FOR NEW LICENSE

ROUTING

NAME/SYMBOL

INT

SUMMARY

① DOES APPLICANT WISH TO COMBINE WITH LICENSE 21-14826-02? - LICENSEE WANTS NEW LICENSE. MANAGEMENT IS SEPARATE FROM LICENSE 21-14826-02.

② NEED DUTIES FOR R.S.O. ✓

③ WRONG SEALED SOURCE LISTED FOR CESIUM-137. (CAN CONDITION) ✓

④ FILM BADGE SERVICE - HOW OFTEN EXCHANGED. - TYPE OF BADGE TLD - WHOLE BODY FILM - NEUTRON CAPABILITY (CAN CONDITION)

⑤ SKETCH OF STORAGE AREA, AND ADJACENT AREAS. ✓ IS GAUGE STORED IN THE CLOSED POSITION. (CAN CONDITION)

METHOD TO PREVENT REMOVAL.

ACTION REQUIRED

FILE

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

DATE

W.P. REICHHOLD

W.P. Reichhold

1/10/85

ACTION TAKEN

SIGNATURE

TITLE

DATE

- ⑥ LEAK TEST KIT — WHO ANALYZES LEAK TEST
- ⑦ EXPAND EMERGENCY PROCEDURES.
- ⑧ WHO WILL PERFORM REPAIR AND MAINTENANCE ON GAUGE.
- ⑨ TRANSPORTATION OF GAUGE TO JOB SITES.
- ⑩ STORAGE AT TEMPORARY JOB SITES (NOT APPLICABLE WON'T LEAVE OVER NIGHT)
- ⑪ ANY EQUIPMENT STORED AT 8221 W. DAVISON STREET?
KANARZ CLAIMS **NO** EQUIPMENT AT THAT LOCATION.
- ⑫ MISSING RADIATION SAFETY PROGRAM.

Called 3/29/85: JIM CRANE: STILL NEED REST OF
RADIATION SAFETY PROGRAM.
WILL SEND - CONTROL 7776.

Called 4/5/85: MIKE KANARZ: STILL NEED REST OF
RADIATION SAFETY PROGRAM - WILL SEND
- CONTROL 7776.

Called 5/13/85: CAN CONDITION AS NOTED.