



GPU Nuclear Corporation  
Post Office Box 480  
Route 441 South  
Middletown, Pennsylvania 17057-0191  
717 944-7621  
TELEX 84-2386  
Writer's Direct Dial Number:

(717) 948-8461

4410-85-L-0119  
Document ID 0260A

May 28, 1985

TMI Program Office  
Attn: Dr. B. J. Snyder  
Program Director  
US Nuclear Regulatory Commission  
Washington, DC 20555

Dear Dr. Snyder:

Three Mile Island Nuclear Station, Unit 2 (TMI-2)  
Operating License No. DPR-73  
Docket No. 50-320

Technical Evaluation Report for the Defueling Water Cleanup System

Per discussions with a member of your staff, attached is a revision to Section 3.2.2.4 of the Technical Evaluation Report (TER) for the Defueling Water Cleanup System.

The purpose of the attached revision is to correct and clarify the description of the low level alarm setpoints for the Fuel Transfer Canal.

The System Description for the Fuel Transfer Canal/Spent Fuel Pool Cleanup System will be revised accordingly.

Sincerely,

F. R. Standerfer  
Vice President/Director, TMI-2

8506030283 850528  
PDR ADOCK 05000320  
P PDR

FRS/RDW/eml

Attachment

cc: Deputy Program Director - TMI Program Office, Dr. W. D. Travers

0009  
11