

DRAFT 1
08/08/84

WATERFORD OPEN ISSUE

Task No.: Allegation A-296

Reference No.: 4-84-A-06

Characterization: Contractor failed to visually examine shop pipe welds during hydrostatic tests.

Initial Assessment of Significance: Potential ASME Code violation.

Source:

Approach to Resolution:

1. Review requirements, codes, specifications, etc.
2. Examine vendor's ASME shop inspection reports.
3. Examine contractor hydrostatic testing procedures and documentation.
4. If allegation is proved, refer to LP&L for resolution.
5. If allegation is disproved, close the allegation.

Status: *under* Vendor review.

8510010511 840808
PDR ADOCK 05000382
E PDR

Allegation A-296

- 2 -

Review Lead: L. Shao (RWH)

Support:

Estimated Resources: 1 man - 2 days

Estimated Completion: April 19, 1984

CLOSURE:

Document Name:
A-296

Requestor's ID:
OP17

Author's Name:
LShao/jkh

Document Comments:
Waterford Open Issue - Allegation A-296

Proof and File for E