



"Your Professional Tubular Goods Inspectors"

WELL SITE INSPECTION, INC.  
P.O. BOX 7  
MUSTANG, OK 73064  
(405) 376-5242

ms-16  
71  
Drill Pipe Inspection  
Drill Collar Inspection  
Ultrasonic Magnaflex Magnaglo  
Casing & Tubing Inspection  
Casing & Tubing Drifting  
Cross Roll Pipe Straightening

June 28, 1985

Mr. Jack E. Whitten  
Nuclear Regulatory Commission  
611 Ryan Plaza Suite 1000  
Arlington, Texas 76011

Dear Mr. Whitten:

In response to your letter stating the need for more information, we submit the following diagrams and statements. If more questions should arise, please call collect to the above number.


I appreciate your special attention you have given this matter, trying to speed the process and assisting with information that was needed. Thank you for your continued efforts.

Respectfully,

*Justin McCollough*

Justin McCollough  
Vice President  
JM/mam

Mail Control No. 460654  
Docket No. 030-28723



8508130511 850715  
REQ4 LIC30  
35-23183-01 PDR

460654




WELL SITE INSPECTION, INC.  
P.O. BOX 7  
MUSTANG, OK 73064  
(405) 376-5242

Drill Pipe Inspection  
Drill Collar Inspection  
Ultrasonic Magnaflex Magnaglo  
Casing & Tubing Inspection  
Casing & Tubing Drifting  
Cross Roll Pipe Straightening

"Your Professional Tubular Goods Inspectors"

Item 9, page 7



The pipe inspection unit will be stored in a fenced six acre area. A locked gate & security light will provide additional safety. The device will be in a locked enclosure of the transport vehicle.

Item 10.5, pages 9 and 10

Transport of the pipe inspection unit will be carried out in accordance with D.O.T regulations.

Item 9, page 7

The device will be stored in a locked enclosure of the transport vehicle in a way that will prevent access by unauthorized persons.

Item 10.4, page 9

No. All maintenance will be performed by the manufacturer and/or NRC authorized personel.

Mail Control No. 460654  
Docket No. 030-28723




WELL SITE INSPECTION, INC.  
P.O. BOX 7  
MUSTANG, OK 73064  
(405) 376-5242

Drill Pipe Inspection  
Drill Collar Inspection  
Ultrasonic Magnaflex Magnaglo  
Casing & Tubing Inspection  
Casing & Tubing Drifting  
Cross Roll Pipe Straightening

"Your Professional Tubular Goods Inspectors"

Item 9, page 7



The pipe inspection unit will be stored in a fenced six acre area. A locked gate & security light will provide additional safety. The device will be in a locked enclosure of the transport vehicle.

Item 10.5, pages 9 and 10

Transport of the pipe inspection unit will be carried out in accordance with D.O.T regulations.

Item 9, page 7

The device will be stored in a locked enclosure of the transport vehicle in a way that will prevent access by unauthorized persons.

Item 10.4, page 9

No. All maintenance will be performed by the manufacturer and/or NRC authorized personel.

Mail Control No. 460654  
Docket No. 030-28723