

August 12, 1986

Dear Mr. Harry J. Pattengill

Enclosed are photographs of the  
Lucky Boy pilot plant operation at the  
present time.

After Orotec Corporation removes  
the plant components burial will be  
completed and the area will be  
landscaped.

photos 1-4 Plant after clean-up

photos 5-7 Panorama of leach pad  
and burial site.

photo 8 overview of plant and  
burial site

photos 9-11 panorama of plant,  
burial area and burial site.

photo 12 overview of disposal pond  
after burial

photos 13-14 panorama of disposal  
pond after burial

Sincerely,

Shamund. Hays, G.P.

OFFICIAL DOCKET COPY



819

40-8752

This is a couple photos that have returned from the lab. others should be ready any day —

Note leached ore being pushed into hole on burial disposal site and disposal site covered with  $\approx$  5 feet of limestone material

# 772



Thomas A. Clary  
P.O. Box 2513  
Globe, Arizona 85502

**CERTIFIED**

P 055 187 296

**MAIL**



Mr. Harry J. Pettingill  
Nuclear Regulatory Commission  
Region IV  
Uranium Recovery Field Office  
Box 25325  
Denver, Colorado 80225