

November 14, 1996

Mr. Erwin J. Odeal
Executive Director
Northeast Ohio Regional Sewer District
3826 Euclid Avenue
Cleveland, OH 44115-2504

SUBJECT: ROUTINE INSPECTION OF THE NORTHEAST OHIO REGIONAL SEWER
DISTRICT SOUTHERLY WASTEWATER TREATMENT PLANT (REPORT
NO. 999-90003/96001(DNMS))

Dear Mr. Odeal:

This refers to the routine inspection conducted by Mr. David Nelson on October 11, 1996, at the Northeast Ohio Regional Sewer District Southerly Wastewater Treatment Plant. The purpose of the inspection was to determine whether activities at the site were conducted safely and in accordance with NRC requirements.

The enclosed copy of our inspection report identifies the areas examined during the inspection. Within these areas, the inspection consisted of observations made during a tour of the South Fill Area located south of the Southerly Wastewater Treatment Plant and interviews with Northeast Ohio Regional Sewer District and B. Koh and Associates, Inc., personnel.

No violations of NRC requirements were identified during this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by

Cynthia D. Pederson, Director
Division of Nuclear Materials Safety

Enclosure: Inspection Report
No. 999-90003/96001(DNMS)

cc w/encl: T. Adams, B. Koh & Associates

bcc w/encl: PUBLIC (IE07)

DOCUMENT NAME: R:\INSPRPTS\DECONTAMIN\96001.DNM

To receive a copy of this document, indicate in the box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII	RIII	RIII	
NAME	Nelson:ib	Jorgensen	Pederson	
DATE	11/7/96	11/12/96	11/14/96	

9611200073 961114
REG3 QA999 ELONORTE
99990003 PDR