



**Jack C. Hicks**  
Manager, Regulatory Affairs

**Comanche Peak  
Nuclear Power Plant  
(Vistra Operations  
Company LLC)**  
P.O. Box 1002  
6322 North FM 56  
Glen Rose, TX 76043

T 254.897.6725

CP-202000433  
TXX-20068  
August 6, 2020

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Ref 10 CFR 50.55a

Subject: Comanche Peak Nuclear Power Plant (CPNPP)  
Docket No. 50-446  
Inservice Inspection (ISI) Owner's Activity Report (OAR-1 Form) for Unit 2 Refueling  
Outage 18 (2RF18)

Dear Sir or Madam:

Vistra Operations Company LLC ("Vistra OpCo") hereby submits the enclosed Inservice Inspection (ISI) Owner's Activity Report (OAR-1 Form) covering ISI activities associated with the Comanche Peak Nuclear Power Plant (CPNPP) Unit 2 Refueling Outage 18 (2RF18). The enclosed reports are provided pursuant to the ASME Boiler and Pressure Vessel Code, Section XI.

This communication contains no new commitments regarding CPNPP Unit 2.

Should you have any questions, please contact Jim Barnette at (254) 897-5866 or [james.barnette@luminant.com](mailto:james.barnette@luminant.com).

Sincerely,

  
\_\_\_\_\_  
Jack C. Hicks

Enclosure: Form OAR-1 Owner's Activity Report for CPNPP Unit 2 ISI - 2RF18

c (email) - Scott Morris, Region IV [Scott.Morris@nrc.gov]  
Dennis Galvin, NRR [Dennis.Galvin@nrc.gov]  
John Ellegood, Senior Resident Inspector, CPNPP [John.Ellegood@nrc.gov]  
Neil Day, Resident Inspector, CPNPP [Neil.Day@nrc.gov]  
Brian Welch, ANII, Comanche Peak [brian\_welch@hsb.com]

**FORM OAR-1 OWNER'S ACTIVITY REPORT**

Report Number CPNPP Unit 2 ISI - 2RF18

Plant Comanche Peak Nuclear Power Plant - P.O. Box 1002 - Glen Rose, Texas 76043

Unit No. 2 Commercial service August 3, 1993 Refueling outage 18

Current inspection interval 3<sup>rd</sup>  
(1<sup>st</sup>, 2<sup>nd</sup>, 3<sup>rd</sup>, 4<sup>th</sup>, other)

Current inspection period 2<sup>nd</sup>  
(1<sup>st</sup>, 2<sup>nd</sup>, 3<sup>rd</sup>)

Edition and Addenda of Section XI applicable to the inspection plan 2007 Edition, 2008 Addenda

Date and revision of inspection plan Unit 2 ISI Program Plan, Interval 3 Rev. 2, December 20, 2018


Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan.

Code Cases Used N-532-4, N-722-1  
(If applicable)

**CERTIFICATE OF CONFORMANCE**

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of 2RF17 conform to the requirements of Section XI.

Signed

 MANAGER, ENGINEERING PROGRAMS  
Owner or Owner's Designee, Title

Date

8/4/20**CERTIFICATE OF INSERVICE INSPECTION**

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State of Province of Texas and employed by Hartford Steam Boiler Inspection and Insurance Company of Connecticut, have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Inspector's Signature

Date

8-4-20

Commissions

NB 12581 AI, B, C, I, N, NS, NSC, NSI / TX 1717

National Board, State, Province and Endorsements

**TABLE 1**  
**ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT**  
**REQUIRED EVALUATION FOR CONTINUED SERVICE**

Examination Category and Item Number	Item Description	Evaluation Description
B-P, B15.10	Steam Generator 2-01, 2-02 and 2-03 Primary Manway Bolting	EV-CR-2020-002913-3
B-P, B15.10	Seal Table fitting	EV-CR-2020-003653-1
D-B, D2.10	Motor Driven Auxiliary Feedwater Pump 2-02 Casing Vent Pipe threaded connection	EV-CR-2020-003649-1

**TABLE 2**  
**ABSTRACT OF REPAIRS, REPLACEMENTS, OR CORRECTIVE MEASURES**  
**REQUIRED FOR CONTINUED SERVICE**

Code Class	Item Description	Description of Work	Date Completed	Repair/ Replacement Plan Number
N/A	N/A	N/A	N/A	N/A