



Entergy Operations, Inc.
17265 River Road
Killona, LA 70057-3093
Tel 504 464 3786

Paul Wood
Manager – Regulatory Assurance
Waterford 3

W3F1-2021-0007

January 29, 2021

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Subject: Submittal of Owner's Activity Report Form for Inservice
Inspection Performed During Operating Cycle 23 / Refuel 23
Waterford Steam Electric Station, Unit 3
Docket No. 50-382
Renewed Facility Operating License No. NPF-38

Attached is the subject report which covers the Owner's Activity Report Form, OAR-1, for Waterford 3 Operating Cycle 23 / Refuel 23, enclosed as Attachment 1. This report is being submitted in accordance with ASME Code Case N-532-5, "Repair/Replacement Activity Documentation Requirements and Inservice Summary Report Preparation and Submission," which was adopted for use at Waterford 3 commencing its incorporation into Regulatory Guide 1.147 and subsequent revision to CEP-RR-001 "ASME Section XI Repair/Replacement Program" on September 8, 2020.

The OAR-1 form is prepared and certified upon completion of each refueling outage and submitted within 90 calendar days of the completion of the refueling outage. This OAR-1 form provides: (1) a listing of items with flaws or relevant conditions that exceeded the acceptance criteria of Division 1 and that required evaluation to determine acceptability for continued service and (2) an abstract for repair/replacement activities that were required due to an item containing a flaw or relevant condition that exceeded Division 1 acceptance criteria. A copy of this letter and the attached report is also being submitted to the office of the Louisiana State Fire Marshall.

There are no new commitments contained in this submittal.

Please contact Paul Wood, Regulatory Assurance Manager, at (504) 464-3786 should you have any questions regarding this submittal.

Respectfully,

PW/llb

Attachment: 1. Owner's Activity Report for Inservice Inspection Performed During
Operating Cycle 23/ Refuel 23

cc: NRC Region IV Regional Administrator
NRC Senior Resident Inspector – Waterford 3
NRC Project Manager – Waterford 3

Mr. H. “Butch” Browning, Jr.
Office of the State Fire Marshall
8181 Independence Blvd.
Baton Rouge, LA 70806

ATTACHMENT 1

To

W3F1-2021-0007

Owner's Activity Report for Inservice Inspection
Performed During Operating Cycle 23 / Refuel 23

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number _____ Cycle 23 / Refuel 23
Plant _____ Waterford Steam Electric Station, 17265 River Road, Killona, LA 70057
Unit No. _____ 3 _____ Commercial service date _____ 9/24/1985 _____ Refueling outage no. _____ 23
(if applicable)
Applicable inspection interval _____ 4th _____
(1st, 2nd, 3rd, 4th, other)
Applicable inspection period _____ 1st _____
(1st, 2nd, 3rd)
Edition and Addenda of Section XI applicable to the inspection plans _____ 2007 Edition Through 2008 Addenda
Date and revision of inspection plans _____ 8/18/2020 Revision 009 SEP-ISI-104
Edition and Addenda of Section XI applicable to repair/replacement activities, if different than the inspection plans
Same as above
Code Cases used for inspection and evaluation: _____ N-532-5
(if applicable)

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of _____ Refuel 23 _____ conform to the requirements of the ASME Code, Section XI.
(refueling outage number)

Signed _____ Jacob Shackelford _____ Date _____ 1/29/21
(Owner or Owner's Designee, Title)

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and employed by _____ Hartford Steam Boiler Inspection and Insurance Company _____ of _____ Connecticut _____ have inspected the items described in this Owner's Activity Report and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of the ASME Code, Section XI.

By signing this certificate, neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluations described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or loss of any kind arising from or connected with this inspection.

(Inspector's Signature) Commission _____ 13976 IN _____
(National Board Number and Endorsement)
Date _____ 1/29/21 _____

CASES OF ASME BOILER AND PRESSURE VESSEL CODE

TABLE 1

**ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED
EVALUATION FOR CONTINUED SERVICE**

Examination Category and Item Number	Item Description	Evaluation Description
None	None	None

CASES OF ASME BOILER AND PRESSURE VESSEL CODE

TABLE 2

ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE

Code Class	Item Description	Description of Work	Date Completed	Repair/Replacement Plan Number
2	2CH1-30 Misc Charging Pump Suction Drain Line	2CH1-30 Pipe Repair	8/2/2019	19-RR-25