

# FEDERAL NOTIFICATION LETTER

Wednesday, October 14, 2020

Director of FSME  
Attn: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

**From General Licensee:**

Grape Drive Moses Lake  
925 N. Grape Dr.  
Moses Lake, WA 98837

**To Specific Licensee:**

SRB Technologies, Inc.  
2580 Landmark Drive  
Winston-Salem, NC 27103  
(336)-659-2610  
Radioactive Materials License #034-0534-2

<b>Date of Transfer:</b> (Enter Date Disposal Box was shipped to Specific Licensee)	11/3/2020
--	-----------

**Description of Device(s) Transferred:**

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

<b>Printed Name:</b>	Melissa Rosenlund
<b>Signature:</b>	Melissa Rosenlund
<b>Phone Number:</b>	360-546-5155

**FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT**

VEOLIA USE ONLY

Sales Order #: 2194449  
Case #: 00030554  
Box 1 of 2

VEOLIA USE ONLY

RGA #: 998564  
RGA # Expiration Date: 1/6/21  
UCN: 1U51387V-5W56442X  
Fedex Tracking #: 691191700010584

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT OR LIFE RATING
1. SRB TECHNOLOGIES	B100	680565	Apr-03	20
2. SBR TECHNOLOGIES	B100	680566	Apr-03	20
3. SBR TECHNOLOGIES	B100	652987	Jan-00	20
4. SBR TECHNOLOGIES	B100	680506	Apr-03	20
5. SBR TECHNOLOGIES	B100	680505	Apr-03	20
6. SBR TECHNOLOGIES	B100	652982	Jan-00	20
7. SBR TECHNOLOGIES	B100	652983	Jan-00	20
8. SBR TECHNOLOGIES	B100	652981	Jan-00	20
9. SBR TECHNOLOGIES	B100	652985	Jan-00	20
10. SBR TECHNOLOGIES	B100	652986	Jan-00	20

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature:



Title: Service Manager

Print Name:

Courtney Reynolds


Date: 9/22/2020

### VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX

Date Received:

9-28-20

Checked In by:



VEOLIA USE ONLY

VEOLIA USE ONLY

Sales Order #: 2194449  
Case #: 00030554  
Box 2 of 2

RGA #: 998564  
RGA # Expiration Date: 1/6/21  
UCN: 8Y51386Z-1A56459B  
Fedex Tracking #: 691191700010577

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT OR LIFE RATING
1. SHIELD SOURCE INC.	LTE	X14756	Dec-07	0.426
2. SHIELD SOURCE INC.	LTE	X14754	Dec-07	0.426
3. SHIELD SOURCE INC.	LTE	X14757	Dec-07	0.426
4. SHIELD SOURCE INC.	LTE	X14752	Dec-07	0.426
5. SHIELD SOURCE INC.	LTE	X14755	Dec-07	0.426
6. SHIELD SOURCE INC.	LTE	X14753	Dec-07	0.426
7. SHIELD SOURCE INC.	LTE	X14758	Dec-07	0.426
8. SRB TECHNOLOGIES	B100	N/A	N/A	20


Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

All are working  
No damage

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature:



Title: Service Manager

Print Name:

Courtney Reynolds

Date: 9/22/2020

### VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received:

9-22-20

Checked in by:

