

## **Appendix B.**

### **Photographs**

**Appendix B. Photographs**

**Contents**

<b>Photos</b>	<b>Section.....</b>	<b>Page</b>
<b>01 – 17</b>	<b>Cell Excavation .....</b>	<b>B-1</b>
<b>18 – 64</b>	<b>RRM.....</b>	<b>B-10</b>
<b>65 – 72</b>	<b>Interim Cover .....</b>	<b>B-34</b>
<b>73 – 80</b>	<b>Spoils Embankment .....</b>	<b>B-38</b>

## Appendix B. Photographs – Cell Excavation



*Photo 1. Phase 3 Cell Excavation October 2020*



*Photo 2. Phase 3 Cell Excavation October 2020*

## Appendix B. Photographs – Cell Excavation (*continued*)



*Photo 3. Phase 3 Cell Excavation October 2020*



*Photo 4. Phase 3 Cell Excavation October 2020*



## Appendix B. Photographs – Cell Excavation (*continued*)



*Photo 5. Cell Excavation November 2020*



*Photo 6. Cell Excavation November 2020*

## Appendix B. Photographs – Cell Excavation (*continued*)



*Photo 7. Cell Excavation November 2020*



*Photo 8. Cell Excavation November 2020*



## Appendix B. Photographs – Cell Excavation (*continued*)



*Photo 9. Cell Excavation December 2020*



*Photo 10. Cell Excavation December 2020*

## Appendix B. Photographs – Cell Excavation (*continued*)



*Photo 11. Cell Excavation December 2020*



*Photo 12. Cell Excavation December 2020*



## Appendix B. Photographs – Cell Excavation (*continued*)



*Photo 13. Cell Excavation January 2021*




*Photo 14. Cell Excavation January 2021*

## Appendix B. Photographs – Cell Excavation (*continued*)



*Photo 15. Cell Excavation February 2021*



*Photo 16. Cell Excavation February 2021*

## Appendix B. Photographs – Cell Excavation (*continued*)



*Photo 17. Completed Cell Excavation February 2021*



## Appendix B. Photographs – RRM



*Photo 18. Dozer placing material October 2020*



*Photo 19. Placement of RRM October 2020*

## Appendix B. Photographs – RRM (*continued*)



*Photo 20. View looking North October 2020*



*Photo 21. RRM Loadout November 2020*



## Appendix B. Photographs – RRM (*continued*)



*Photo 22. RRM ready for placement November 2020*



*Photo 23. RRM placement November 2020*



## Appendix B. Photographs – RRM (*continued*)



*Photo 24. RRM Compaction December 2020*



*Photo 25. Breaking up Frost December 2020*

## Appendix B. Photographs – RRM (*continued*)



*Photo 26. Loading RRM December 2020*



*Photo 27. Placing a Debris Lift December 2020*



## Appendix B. Photographs – RRM (*continued*)



*Photo 28. RRM Debris Lift December 2020*



*Photo 29. Material being placed December 2020*



## Appendix B. Photographs – RRM (*continued*)



*Photo 30. Lift Prepared for In-place Density Test January 2021*



*Photo 31. Snow and Frost Removal January 2021*

## Appendix B. Photographs – RRM (*continued*)



*Photo 32. Equipment Placing RRM January 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 33. Cell Operations February 2021*



*Photo 34. Pushing Soils While Snowing February 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 35. Soils Placement February 2021*



*Photo 36. RRM Lift February 2021*

## Appendix B. Photographs – RRM (*continued*)



*Photo 37. Aerial Picture of Disposal Cell March 2021*



*Photo 38. Debris Being Covered March 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 39. RRM Loadout March 2021*



*Photo 40. RRM Lifts March 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 41. Hauling RRM for Placement April 2021*



*Photo 42. RRM Loadout April 2021*

## Appendix B. Photographs – RRM (*continued*)



*Photo 43. Loader Loading Material in Haul Truck April 2021*



*Photo 44. Equipment Placing RRM Material on Lift Area April 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 45. Aerial Photo of RRM being Placed May 2021*



*Photo 46. RRM Placement May 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 47. Placement of Material on Lift Area by Haul Truck May 2021*



*Photo 48. Preparing for Sand Cone Testing May 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 49. Placing RRM June 2021*



*Photo 50. Dozer Placing RRM on Active Lift Area June 2021*

## Appendix B. Photographs – RRM (*continued*)



*Photo 51. Haul Truck Dumping RRM of Lift Area June 2021*



*Photo 52. Watering Area for Dust Control June 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 53. Multiple Disposal Cell Operations July 2021*



*Photo 54. Hauling RRM for Placement July 2021*

## Appendix B. Photographs – RRM (*continued*)



*Photo 55. Equipment Preparing RRM Lift July 2021*



*Photo 56. Dozer used for RRM Lifts July 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 57. Compaction of 4<sup>th</sup> RRM Lift in Top 7 Feet August 2021*



*Photo 58. RRM Placement August 2021*

## Appendix B. Photographs – RRM (*continued*)



*Photo 59. Dozer Pushing Material on RRM Lift August 2021*



*Photo 60. Looking South at the Disposal Cell August 2021*



## Appendix B. Photographs – RRM (*continued*)



*Photo 61. Placement of Debris Lift September 2021*



*Photo 62. Dust Suppression and Moisture Conditioning September 2021*

## Appendix B. Photographs – RRM (*continued*)



*Photo 63. Pushing and Dumping RRM September 2021*



*Photo 64. Pushing RRM September 2021*



## Appendix B. Photographs – Interim



*Photo 65. Aerial of Ongoing Interim May 2021*



*Photo 66. Aerial of Interim Placement May 2021*

## Appendix B. Photographs – Interim (*continued*)



*Photo 67. Pushing Interim May 2021*



*Photo 68. Pushing Out of the Stock Pile May 2021*



## Appendix B. Photographs – Interim (*continued*)



*Photo 69. Interim Loadout June 2021*



*Photo 70. Interim Protective Cover Haul June 2021*

## Appendix B. Photographs – Interim (*continued*)



*Photo 71. Dozer Pushing Interim Cover Material June 2021*



*Photo 72. North Side Interim June 2021*



## Appendix B. Photographs – Spoils Embankment



*Photo 73. Constructing Spoils Embankment October 2020*



*Photo 74. Placing Spoils Embankment Lift October 2020*

## Appendix B. Photographs – Spoils Embankment (*continued*)



*Photo 75. Spoils Embankment Construction October 2020*



*Photo 76. Hauling Material for Placement on Spoils Embankment November 2020*



## Appendix B. Photographs – Spoils Embankment (*continued*)



*Photo 77. Constructing Spoils Embankment November 2020*



*Photo 78. Transporting Material to Spoils Embankment December 2020*

## Appendix B. Photographs – Spoils Embankment (*continued*)



*Photo 79. Transporting Material to Spoils Embankment January 2021*



*Photo 80. Scraper Hauling Spoils Embankment Material January 2021*