

Location: 4 th Floor Mens Bathroom			RWP# EML#02			Survey# DHS EML 2009-002			Survey Type: Release			pg. 1 of 1		
Smear (CPM/100 cm ²)			circle one <input checked="" type="checkbox"/>											
Direct Count (CPM/Direct Frisk)														
No.	α	β												
1														
2														
3														
4														
5														
6														
7														
8														
9														
10														
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														

29-29 Statics

① 0/51	⑦ 0/171
② 0/50	⑧ 1/197
④ 0/37	⑨ 2/206
⑩ 0/38	⑩ 2/189
⑪ 0/49	⑪ 3/206
⑫ 0/37	⑫ 3/202
⑬ 0/49	⑬ 7/265

Comparative Ceramic tile static values

Floor { ① 2/209 - unglazed tile
 ② 5/238

wall { ③ 14/291 - glazed tile

Comments	Surveyed By:	Date:	Instrument	Serial #	α Eff.	β Eff.	α Bkg.	β Bkg.	γ Bkg.	Cal. Due	Key	
	Dan Cote	2/26/09	22-29	180830	0.387	0.224	0.2	41.5	n/a	2/3/10		
			43-10-1								■ A/S Location	
			23-60	145481	0.17	0.061	0	108	n/a	11/12/09	.. Boundary	
			43-89	BR154732							○ Smear	
			Bicron	C854F	n/a	n/a	n/a	n/a	6		□ Dose Rate <u>u</u> /hr	
	Reviewed By:	Date:									• Direct Reading CPM/direct frisk	
	Nicholas M. Berliner	12/28/11	Original survey misplaced									△ Grab Sample